

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
800 BITTING BUILDING  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM  
File One Copy

Lease Owner Fred B. Anschutz Address 709 Union National Bank Bldg.  
(Applicant)

Lease (Farm Name) Barstow Well No. 1

Well Location NE NE NE Sec. 26 Twp. 22 Rge. 16 (E)-(W) W

County Pawnee Field Name (if any) \_\_\_\_\_

Total Depth 4095' Oil Gas Dry Hole XXXXX

Was well log filed with application? Yes If not, explain: \_\_\_\_\_

Date and hour plugging is desired to begin 5-15-55

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner \_\_\_\_\_

T. D. Sweetman Address Great Bend, Kansas

Plugging Contractor Anschutz Drilling Co., Inc.

Plugging Contractor's License No. \_\_\_\_\_

Address 709 Union National Bank Building

Invoice covering assessment for plugging this well should be sent to \_\_\_\_\_

Fred B. Anschutz Address 709 Union National Bank Bldg.

and payment will be guaranteed by applicant.

RECEIVED  
STATE CORPORATION COMMISSION  
MAY 18 1955

[Signature]  
Applicant or Acting Agent

Date May 17, 1955

PLUGGING  
FILE SEC 26 T 22 R 16  
PAGE 119 LINE 8

CONSERVATION DIVISION  
Wichita, Kansas

5-18-55



STATE OF KANSAS  
 STATE CORPORATION COMMISSION  
 CONSERVATION DIVISION  
 800 BITTING BUILDING  
 WICHITA 2, KANSAS

May 17, 1955  
 211 N. Broadway

Well No.	1
Lease	Barston
Description	NE NE NE 26-22-16W
County	Pawnee
File No.	119-8

Anschutz Drilling Company, Inc.,  
 709 Union National Bank Bldg.,  
 Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Warren H. Horner, Box 207, Great Bend, Kansas.

STATE CORPORATION COMMISSION  
 CONSERVATION DIVISION

BY:

*J. P. Roberts*  
 J. P. ROBERTS

cc: District Plugging Supervisor