

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Transit Corporation Address Oklahoma City, Okla.
(Applicant)

Lease (Farm Name) Hirsch Well No. 1

Well Location NE NE NW Sec. 23 Twp. 22 Rge. 15 (X)-(W)

County Pawnee Field Name (if any) _____

Total Depth 4023 Oil Gas Dry Hole x

Was well log filed with application? Yes . If not, explain: _____

Date and hour plugging is desired to begin At once

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired. (Use an additional sheet if necessary) _____

Name of the person on the lease in charge of well for owner _____

J. C. Dinger, Jr., Address Great Bend, Kansas.

Name of Plugging Contractor Transit Corporation

Address 1516 Liberty Bank Bldg., Oklahoma City, Okla.

Invoice covering assessment for plugging this well should be sent to

Transit Corporation Address Oklahoma City, Oklahoma.

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

J. C. Dinger, Jr.
Applicant or Acting Agent

Date May 19, 1955

PLUGGING
FILE REC 23 T 22 R 15
PAGE 119

5-20-55



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION

800 BITTING BUILDING
WICHITA 2, KANSAS

May 17, 1955
211 N. Broadway

Well No.	1
Lease	Hirsch
Description	NE NE NW 23-22-15W
County	Pawnee County
File No.	File No. 119-9

Transit Corporation
1516 Liberty Bank Bldg.,
Oklahoma City, Oklahoma

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Warren H. Harner, Box 207, Great Bend, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY:

J. P. Roberts
J. P. ROBERTS

cc: District Plugging Supervisor