

KCC OIL/GAS REGULATORY OFFICES

Inspection Date 01/26/2017 District: 3 Incident Number: 5668

- ☐ New Situation ☐ Lease Inspection
☒ Response to Request ☐ Complaint
☐ Follow-up ☒ Field Report

Operator License No: 6279 API: 15-207-23116-00-01 Q3 SW Q2: NE Q1: NE

Operator Name: Patrick Development Corp. SEC 19 TWP 26 RGE 17 RGEDIR E

Address: 3408 W 93 Rd

FSL: 4450

City: Leawood

FEL: 975

State KS Zip Code: 66206

Lease: Gray

Well No.: N-15

Phone contact: 913-375-8368

County: WO

Reason for Investigation:

To try and locate well and determine the status of the well.

Problem:

No well at the location provided.

Persons contacted:

James Haclarod, pumper, 620-363-0062

Findings:

I met with James Haclarod, pumper for Patrick Development, to try and locate well #N-15 on the Gray Lease. KCC staff had previously tried to locate this well and noted with a field report that this well was not at the given location. Mr. Haclarod and I looked for the well and determined there was no well at this location.

Actions / Recommendation

Follow-up Required ☐

Deadline Date:

Refer my findings to Larry Marchant, District #3 UIC Coordinator, and recommend that this well be removed from Docket #E-08990 and removed from Patrick Development License.

Photo's Taken:

0

☒ RBDMS

☐ KGS

☐ TA DBF

Report Prepared By: Ryan Duling

☐ T1 DBF

☒ District Files

☐ Courthouse

Position: E.C.R.S.

KCC OIL/GAS REGULATORY OFFICES

Inspection Date 08/24/2015 District: 3 Incident Number: 5391

- ☒ New Situation ☐ Lease Inspection
☐ Response to Request ☐ Complaint
☐ Follow-up ☒ Field Report

Operator License No: 6279 API: 15-207-23116-00-01 Q3 SW Q2: NE Q1: NE
Operator Name: Patrick Development Corporat SEC 19 TWP 26 RGE 17 RGEDIR E
Address: 3408 W. 93rd St. FSL: 4450
City: Leawood FEL: 975
State KS Zip Code: 66206 Lease Gray Well No.: N 15
Phone contact: 913-381-2814 County: WO

Reason for Investigation:

A MIT was due for well #N 15. Well could not be located at the time the test was suppose to be performed. Staff went back to investigate and try to locate well. Docket #E-08990

Problem:

No well at the listed location.

*Rose Oil Prop
NENE 165 FNL 165 FEL*

Persons contacted:

*MIT due
8/10/2015*

Findings:

Larry Marchant, District #3 UIC Coordinator, and I arrived on location in the morning of 08/24/2015. I downloaded the coordinates for well #N 15 into the gps device. We arrived at the correct site were well # N15 was suppose to be drilled. No well was present at this location. A metal detector was used and no well could be located in area 100' from the desired location.

Actions / Recommendation

Follow-up Required ☐

Deadline Date:

The operator needs to locate the well or turn in an U-5 and cancel the authorization for this well.

Photo's Taken: 0

☒ RBDMS ☐ KGS ☐ TA DB Report Prepared By Ryan Duling
☐ T1 DBF ☒ District Files ☐ Courthouse Position: PIRT II