

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner E. H. Adair, et al Address 1019 East Second Street, Wichita 7, Kansas.
(Applicant)

Lease (Farm Name) ROGERS Well No. 2.

Well Location SW SW SE Sec. 35 Twp. 22 Rge. 12 ~~(E)~~ (W)

County STAFFORD Field Name (if any) _____

Total Depth 3680 feet Oil Gas Dry Hole (Dry hole)

Was well log filed with application? Yes. If not, explain: _____

Date and hour plugging is desired to begin 6-28-56.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____
Orval Bridge Address 507 Union National Bldg., Wichita, 2, Kans.
~~Harry Adair~~ ~~1019 East Second Street, Wichita 7, Kansas.~~

Plugging Contractor Murfin Drilling Company

Plugging Contractor's License No. _____

Address 507 Union National Bank Bldg., Wichita 2, Kansas.

Invoice covering assessment for plugging this well should be sent to _____

E. H. Adair Oil Company Address 1019 East Second Street, Wichita 7, Kansas.

and payment will be guaranteed by applicant.

7-12-56

Sherrill Compton
Applicant or Acting Agent
Sherrill Compton.

Date June 28, 1956.

PLUGGING			
FILE	SEC	T	R
	35	22	12W
BOOK	PAGE	LINE	
	76	9	



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS

July 2, 1956

Well No.	2
Lease	Rogers
Description	SW SW SE 35-22-12W
County	Stafford
File No.	76-9

E. H. Adair Oil Co.
 1019 E. Second
 Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. M. Brundage, Box 283, Hoisington, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

By S. S. Greider
 S. S. Greider
 WELL PLUGGING SUPERVISOR

cc:
 District Plugging Supervisor