

Conservation Division
266 N. Main St., Ste. 220
Wichita, KS 67202-1513



Phone: 316-337-6200
Fax: 316-337-6211
<http://kcc.ks.gov/>

Jay Scott Emler, Chairman
Shari Feist Albrecht, Commissioner
Pat Apple, Commissioner

Sam Brownback, Governor

January 3, 2017

L.D. Drilling, Inc.
7 SW 26th Ave.
Great Bend, KS 67530

Re: Casey 2-7
SE/4 Sec. 07-02S-37W
Cheyenne County, Kansas
15-023-21446-00-00

Dear Sir or Madam:

This letter is to inform you that you have been granted an extension of time in which to close the drilling pits associated with the Casey 2-7 well.

The original 365 days for closure expired on 10/14/2016. This extension will expire on 04/03/2017. We urge you to make every effort to close these pits within this time frame. In the event there is water standing in these pits, please dewater and dispose of fluids in an authorized disposal facility to expedite closure. Extension of this time frame automatically extends the time period for filing the closure of surface pit form, **but not the time period for filing the waste transfer form (CDP-5).**

*Failure to close the pit or request an additional extension prior to the expiration date shall result in a monetary penalty in accordance with K.A.R. 82-3-602(a). An additional pit extension may be renewed upon request, but **no pit permit extension shall be extended beyond six months after the original deadline.***

Please complete the pit closure form (CDP-4) through Kolar (Kansas On-Line Automated Reporting) at <https://kolar.kgs.ku.edu>.

If you have any questions in this regard, please do not hesitate to contact Kathy Haynes at (316) 337-6243.

Sincerely,

Ryan A. Hoffman
Director

Cc: File
District

L.D. DRILLING, INC.

7 S.W. 26TH AVE.

OFFICE PHONE 620-793-3051

GREAT BEND, KS 67530



December 29, 2016

Director
Kansas Corporation Commission
Conservation Division
266 N Main St. Ste 220
Wichita, KS 67202-1513

Re: Casey #2-7
API #15-023-21446-00-00

Dear Director

Please allow us 6 months extension on filling the pit on the Casey 2-7. Our dozer operator checked the condition of the drilling pit recently and it still has water in it. Since it was checked we had more moisture in that area. The Casey #2-7 pit is not dried out and can't be filled at this time. Please allow us more time to fill it. Thank you for your consideration for this extension.

Sincerely

Marilyn Davis