

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

15-009-15694-0000

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Harry Gore Address 400 Brown Bldg. Wichita, Ks.
(Applicant)

Lease (Farm Name) Stull Well No. 3

Well Location NW SE SW Sec. 6 Twp. 16 Rge. 12 (~~E~~)-(W)

County Barton Field Name (if any) _____

Total Depth 3350 Oil Gas Dry Hole

Was well log filed with application? no. If not, explain: _____

Log will be filed with plugging record

Date and hour plugging is desired to begin August 1, 1954

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.
(Use an additional sheet if necessary) _____

Name of the person on the lease in charge of well for owner _____

Cleo Combs Address Box 162, Russell, Ks.

Name of Plugging Contractor To be supplied on plugging record

Address _____

Invoice covering assessment for plugging this well should be sent to

Harry Gore Address 400 Brown Bldg., Wichita, Ks.

and payment will be guaranteed by applicant.

RECEIVED

STATE CORPORATION COMMISSION

JUL 22 1954

07-22-54

Therese B. Partner
Applicant or Acting Agent

Date July 21, 1954

PLUGGING

FILE SEC 6 T 16 R 12W
BOOK PAGE 50 LINE 1600

CONSERVATION DIVISION
Wichita, Kansas



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

July 22, 1954

Well No.	3
Lease	Stull
Description	NW SE SW 6-16-12W
County	Barton
File No.	50-15

Harry Gore
400 Brown Bldg.
Wichita, Kansas

Dear Sir:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr.

Warren H. Horner, Box 207, Great Bend, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: J. P. Roberts
J. P. ROBERTS

cc: District Plugging Supervisor