Well Total Depth #/DSC feet 2/3/82 Conductor Pipe: Size feet Surface Casing: Size feet J,004 Abandoned Oil Well X Gas Well Input Well SWD Well D6A Other well as hereinafter indicated Plugging Contractor Kelso Casing Pulling License Number 6050 Address Box 347, Chase, KS 67524 Company to plug at: Hour: 9:00 am Day: 25 Month: January Year:19 84 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomez (company name) Kelso Casing Pulling (phone) 316-938-2416 Were: 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through Dailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement, Signed Machael Machael Signed Machael Machael Signed Machael Machae	To:	ODATION COMMISSION	API NUMBER 15-145-21043-0000
TECHNICAN'S PLUGGING REPORT TECHNICAN'S PLUGGING REPORT Operator: License # 7930 Deparator: Merit Energy Corp. 1730 Energy Center That I True Street Denver, CO 80202 Abandoned 041 Well x Gas Well Input Well SWD Well DSA Other well as hereinafter indicated Plugging Contractor Kelso Casing Pulling Address Box 347, Chase, KS 67524 Company to plug at: Rour: 9:000 as Day: 25 Honth; January Year:19 84 VERBAL FLUGGING ORDERS GIVEN TO Mike Gomes (company name) Kelso Casing Pulling Alicn Sand bottom back to 3720' and dump 4 sx coment on sand through Dailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. By gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Flugging Operations attended by Agent?: All X Part None Operators Completed: Hour: 10:30 as Day: 25 Month: January Year:19 84 ACCUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on Signed Accual Hullourn Report 1st plug sand bottom back to 3720' and dump 4 sx cement on Sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. Flugging Operations attended by Agent?: All X Part None Operators Report 1st plug sand bottom back to 3720' and dump 4 sx cement on Sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. Fig. sx cement. Flugging Operations of the strip of the strip of the sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement on Sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement on Sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement on Sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement on Sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement on sand through bailer. Sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement on sand	CONSERVATI	ON DIVISION - PLUGGING SECTION	SW SE NE , Sec. 10 , T 21 S, R 18 W/X
Deparator License # 7930 Deparator: Merit Energy Corp. Name & 1750 Energy Center 1750 En			feet from N/S section line
Operator: Merit Energy Corp. Name & 1750 Energy Center 1750 Energy Cen	TECHNICIAN	'S PLUGGING REPORT	feet from W/E section line
Operator: Merit Energy Corp. Name & 1750 Energy Center 1750 Energy Cen	Operator L	icense # 7930	Lease Name Fleske Well # 1-10
Name & 1750 Energy Center Address 1750 Energy Center Denver, CO 80202 Conductor Pipe: Size	Operator:	Merit Energy Corp.	
Conductor Pipe: Size feet Surface Casing: Size Feet Surface Casing: SwD well Surface Casi	Name &	1750 Energy Center	
Surface Casing: Size & Heet 1,004 Abandoned Oil Well X Gas Well Input Well SVD Well D&A Other well as hereinafter indicated Plugging Contractor Kelso Casing Pulling License Number 6060 Address Box 347, Chase, KS 67524 Company to plug at: Hour: 9:00 am Day: 25 Month: January Vear:19 84 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomex (company name) Kelso Casing Pulling (phone) 316-938-2416 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomex (company name) Kelso Casing Pulling (phone) 316-938-2416 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomex (company name) Kelso Casing Pulling (phone) 316-938-2416 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomex (company name) Kelso Casing Pulling (phone) 316-938-2416 VERBAL PLUGGING REPORT ORDERS GIVEN TO Mike Gomex Signed All X CECKNICIAN) Signed All X Part None Operations Completed: Hour: 10:30 mb Day: 25 Month: January Year:19 84 ACTUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx bulls, 10 sx gel, 75 sx cement. Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing incomplished the job with 60/40 Pozmix, 25 gel, 35 cc. Maximum pressure 9000 and shut in pressure at 5000. STATE COMPONITION DIMESSON NO ICED E 3-16-84 Signed All All XIII NONE CERNICIPAD Signed All All All All All All All All All Al	Address		
Abandoned 011 Well X Gas Well Input Woll SWD Well D&A Other well as hercinafter indicated Plugging Contractor Kelso Casing Pulling License Number 6050 Address Box 347, Chase, KS 67524 Company to plug at: Hour; 9:00 mm Day: 25 Month: January Year:19 84 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomez (company name) Kelso Casing Pulling (phone) 316-938-2416 vere: 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through pailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Signed Midwal Mi January Flugging Operations Completed: Hour: 10:30 mm Day: 25 Month: January Year:19 84 ACTUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing Recomplished the job with 60/40 Pozmix, 2% rel, 3% cc. Maximum pressure 900f and shut in pressure at 500%. 1 hereby certify that the above plugging instructions were given as hereffer 12 10 10 10 10 10 10 10 10 10 10 10 10 10			
Other well as hereinafter indicated Plugging Contractor Kelso Casing Pulling License Number 6050 Address Box 347, Chase, KS 67524 Company to plug at: Hour; 9:00 am bay: 25 Month: January Year:19 84 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomez (company name) Kelso Casing Pulling (phone) 316-938-2416 were: 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through Dailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. Signed Address Month: January Year:19 84 Flugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 10:30 am Day: 25 Month: January Year:19 84 ACCUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. 15 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing and through the 10 b with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900% and shut in pressure at 500%. STATE Componed 10 of 4 1/2" productions were given as hereff Egypty 10 of		·	Surface Casing: Size 878 feet 1,009
Plugging Contractor Kelso Casing Pulling License Number 6050 Address Box 347, Chase, KS 67524 Company to plug at: Hour; 9:00 am Day; 25 Month; January Year:19 84 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomez (company name) Kelso Casing Pulling (phone) 316-938-2416 VEREAL PLUGGING ORDERS GIVEN TO Mike Gomez (company name) Kelso Casing Pulling (phone) 316-938-2416 VERCE: 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through Dailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Signed Albard Ma Lacony (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 10:30 am Day: 25 Month: January Year:19 84 ACCIDAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. 15 sx cement. 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing and that in pressure at 500%. STATE COMPONDATIONS COMPONDATI	Abandoned	Oil Well X Gas Well Ir	nput Well D&A
Address Box 347, Chase, KS 67524 Company to plug at: Hour: 9:00 am Day: 25 Month: January Year:19 84 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomez (company name) Kelso Casing Pulling (phone) 316-938-2416 were: 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through Dailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Signed Address Month: January Year:19 84 ACTUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing shut in pressure at 500%. STATE COMPONIATION COMMAN COMM	Other well	as hereinafter indicated	
Company to plug at: Hour: 9:00 am Day: 25 Month: January Year: 19 84 VERBAL PLUGGING ORDERS GIVEN TO Mike Gomex (company name) Kelso Casing Pulling (phone) 316-938-2416 WEVER: 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through pailer. 2nd plug pump through head in sequence 3 sx bulls, 10 sx gel, 75 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Signed Manager Manager Manager Month: January Year: 19 84 ACTUAL FLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. They recovered 2810' of 4 1/2" production casing. Sun cementing and that in pressure at 500%. They recovered 2810' of 4 1/2" production casing. Sun cementing and that in pressure at 500%. STATE CORPORATION DOWN COMMAN CO	Plugging C	ontractor Kelso Casing Pulling	License Number 6050
VEREAL FLUGGING ORDERS GIVEN TO Mike Gomez (company name) Kelso Casing Pulling (phone) 316-938-2416 Were: lst pluk sand bottom back to 3720' and dump 4 sx cement on sand through Dailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Signed History M. Joseph (TECHNICIAN) Plugging Operations attended by Agent?: All x Part None Operations Completed: Hour: 10:30 am Day: 25 Month: January Year:19 84 ACTUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. 15 sx gel. 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. They recovered 2810' of 4 1/2" production casing. Sun cementing about in pressure at 500#. State of the plugging instructions were given as herefit stated and that I (did / XXXXXXXX) observe this plugging. N V O I C F D Signed All Alley FORM CP-2/3 FORM CP-2/3 FORM CP-2/3	Address	Box 347, Chase, KS 67524	
(company name) Kelso Casing Pulling (phone) 316-938-2416 were: 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through pailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Signed Radd M. Large (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 10:30 am Day: 25 Month: January Year:19 84 ACTUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement. 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. State Compton Colon I hereby certify that the above plugging instructions were given as hereEff to the compton Colon Wishing Kanasaga N V O I C F D Signed Malland Market FORM CP-2/3 FORM CP-2/3	Company to	plug at: Hour: 9:00 am Day:	25 Month: January Year:19 84
Signed Market 125 sx cement. Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 10:30 am Day: 25 Month: January Year:19 84 ACTUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, Signed Market 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. STATE COMPONATION OF COMM I hereby certify that the above plugging instructions were given as berefit to 180 months of 180 mont	VERBAL PLU	GGING ORDERS GIVEN TO Mike Gome	ez
Signed Remarks: They recovered 2810' of 4 1/2" production casing. Sun cement on sand through salter. 1 hereby certify that the above plugging instructions were given as hereff for the form of the fo	(company n	ame) Kelso Casing Pulling	(phone) 316-938-2416
Signed Remarks: They recovered 2810' of 4 1/2" production casing. Sun cement. Signed bridge and pump another 125 sx cement. Signed Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. Signed Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. State Componential observe this plugging. Signed Remarks: Signed Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing and shut in pressure at 500#. State Componential observe this plugging. Signed Remarks: Signed Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing and shut in pressure at 500#. State Componential observe this plugging. Signed Remarks: Signed Remarks:		1	
Signed Manager			
Operations Completed: Hour: 10:30 am Day: 25 Month: January Year:19 84 ACTUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as herefit stated and that I (did / XXXXXXXXX) observe this plugging. NVOICED Signed Actual M. Lucy FORM CP-2/3			Signed Richard W. Lasen (TECHNICIAN)
ACTUAL PLUGGING REPORT 1st plug sand bottom back to 3720' and dump 4 sx cement on sand through bailer. 2nd plug pump through head in sequence 3 sx hulls, 10 sx gel, 75 sx cement, 15 sx gel, 1 sack hulls and release 8 5/8" plug and pump another 125 sx cement. Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as herefit stated and that I (did / XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Plugging O	perations attended by Agent?: All	X Part None
Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. I hereby certify that the above plugging instructions were given as hereft stated and that I (did / XXXXXXXXX) observe this plugging. N V O I C E D Signed Accompliance 3 sx hulls, 10 sx gel,	Operations	Completed: Hour: 10:30 am Day	7: <u>25</u> Month: <u>January</u> Year:19 <u>84</u>
Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. 2-2-8 STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as herefile stated and that I (did / XMXXXXXX) observe this plugging. CONSERVATION DIVISION NICHAEL RANSAS NVOICED Signed Allow Michita, Kansas FORM CP-2/3	ACTUAL PLU	GGING REPORT 1st plug sand bott	tom back to 3720' and dump 4 sx cement on
Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as herefit stated and that I (did / XXXXXXXXX) observe this plugging. CONSERVATION DIVISION Wichita, Kansas Wichita, Kansas FORM CP-2/3	sand throu	gh bailer. 2nd plug pump throug	th head in sequence 3 sx hulls, 10 sx gel,
Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and shut in pressure at 500#. STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as herefit stated and that I (did / XXXXXXXXX) observe this plugging. CONSERVATION DIVISION Wichita, Kansas Wichita, Kansas FORM CP-2/3	75 sx ceme	ent, 15 sx gel, 1 sack hulls and	release 8 5/8" plug and pump another
Remarks: They recovered 2810' of 4 1/2" production casing. Sun cementing accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and But in pressure at 500#. STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as herefit stated and that I (did / XMXXXXXX) observe this plugging. Signed Ailand A. Juan FORM CP-2/3		·	
Accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and 2-2-8 co. STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as hereif prated and that I (did / XMXXXXXX) observe this plugging. CONSERVATION DIVISION Wichita, Kansas N V O I C E D Signed Achieved M. Licen (TECHNICIAN) FORM CP-2/3			
Accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and 2-2-8 co. STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as hereif prated and that I (did / XMXXXXXX) observe this plugging. CONSERVATION DIVISION Wichita, Kansas N V O I C E D Signed Achieved M. Licen (TECHNICIAN) FORM CP-2/3			
Accomplished the job with 60/40 Pozmix, 2% gel, 3% cc. Maximum pressure 900# and 2-2-8 co. STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as hereif prated and that I (did / XMXXXXXX) observe this plugging. CONSERVATION DIVISION Wichita, Kansas N V O I C E D Signed Achieved M. Licen (TECHNICIAN) FORM CP-2/3		. \	
STATE CORPORATION COMM I hereby certify that the above plugging instructions were given as herefit stated and that I (did / XMXXXXXX) observe this plugging. CONSERVATION DIVISION Signed Richard M. Lucy (TECHNICIAN) FORM CP-2/3	Remarks:	They recovered 2810' of 4 1	2" production casing. Sun cementing
I hereby certify that the above plugging instructions were given as herefit stated and that I (did / XMXXXXXX) observe this plugging. **Conservation observe this plugging.** **Conservation observe this plugging.** **Conservation observe this plugging.** **Conservation observation observe this plugging.** **Conservation observation observations were given as herefit stated of the conservation observation observation observations were given as herefit stated of the conservation observation observations were given as herefit stated of the conservation observation observation observations were given as herefit stated of the conservation observation observat	accomplish	ed the job with 60/40 Pozmix, 29	6 gel, 3% cc. Maximum pressure 900# and
and that I (did / XXXXXXXX) observe this plugging. CONSERVATION DIVISION Wichita, Kansas Signed Richard M. Licen (TECHNICIAN) FORM CP-2/3	shut in pr	essure at 500#.	2-2-80
and that I (did / XXXXXXXX) observe this plugging. CONSERVATION DIVISION Wichita, Kansas Signed Richard M. Licen (TECHNICIAN) FORM CP-2/3			STATE CORPORATION OF
NVOICED Signed Richard M. Lucy (TECHNICIAN) FORM CP-2/3	I her	eby certify that the above pluggir	ng instructions were given as hereif stated
NVOICED Signed Richard M. Lucy (TECHNICIAN) FORM CP-2/3			conserve
NVOICED Signed Richard M. Lucy (TECHNICIAN) FORM CP-2/3			Wichita, Kansan
$E = \frac{\partial - (6 - 84)}{\text{FORM CP-2/3}}$	NVOI	CFD	
	·	-84	(TECHNICIAN)

N