15-145-20692-0000

STATE OF KANSAS

STATE CORPORATION COMMISSION

Give All Information Completely Ma Ma

WELL PLUGGING RECORD

Make Required Affidavit	,	Fawi					
Mail or Deliver Report to	Locati			nty. Sec. " or foota			
Conservation Division	MUGALI			OI TOOLA	·Se Trom 1		
State Corporation Comm.	Leage	Owner -	SE NW			 	
245 North Water	I abac	Owner Bere	<u>en Corpo</u>	ration		Vol 1 N	
Wichita, KS 67202	rease	Wayı	ne #1			Vell No.	
11011ta; 110 0,1102				th Financi			<u> </u>
	Charac	ter of We	11 (Comp	leted as C	Dil, Gas o	or Dry Ho	le)
i i i		I	Dry Hole				
<u> </u>	→ Date W	ell comple	eted	-	Septem	ber 20,	198
	Applic	ation for	pluggin	g filed_	Sentem	her 20.	198
	Applic	ation for	pluggin	g approved	Septem	ber 20.	198
	Pluggi:	ng commend	ced	12:15 P	M, Septem	ber 20,	198
	Pluggi	ng complet	ted	2:00 P	M, Septem	ber 20,	198
1 ! ! !	Reason	for aband	donment	of well or	producin	g format	ion
 	1			Dry Ho			
ı i	If a p	roducing v	well is	abandoned,	date of	last pro	duction
							19
Locals well correctly on above	₩as pe	rmission o	obtained	from the	Conservat	ion Divi	sion or
Locals well correctly on above Section Plat	its ag	ents befor	re plugg	ing was co	mmenced?	Yes	
Name of Conservation Agent wh	ho supervised	plugging	of this	well Ma	rion Schm	idt	
moducing formation	Do	nth to to-	. D	attam	Total De	pth of W	ell 396
how depth and thickness of a	all water, oi	l and gas	formati	ons.			, · · ·
OIL, GAS OR WATER RECORDS						CASING R	ECORD
FORMATION	COMEMME	THOM	ТО	1 CTCP	1		
FORMSTION	CONTENT	. FROM	10-	8 5/8"	PUT IN	PULLEI	
	 	 	 	0 3/8	044	Nor	ıe
		-		 	 	- 	
		 	ļ <u></u>	ļ	ļ		
lugs were used, state the cl	methods used haracter of s	in introduced in introduced in interest in introduced in i	ducing i	t into the	e hold. I	f cement	
was placed and the method or	methods used haracter of s	in introduced in introduced in interest in introduced in i	ducing i	t into the	e hold. I	f cement	or oth
was placed and the method or plugs were used, state the clear feet for each process filled ho	methods used haracter of s plug set	in introduced and demonstrated and demon	ducing i	t into the	e hold. I	f cement	or oth
was placed and the method or plugs were used, state the clean feet for each period for the filled house for each secks	methods used haracter of splug set. le with heavy at 800; 30 s	in introduced and demonstrated and demon	ducing i epth pla	t into the	e hold. I	f cement	or oth
was placed and the method or plugs were used, state the clean feet for each period for each pe	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1	in introduced and and and and and and and and and an	ducing i epth pla	t into the	e hold. I	f cement	or oth
ras placed and the method or plugs were used, state the classic feet for each period feet feet feet feet feet feet feet fee	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath	in introduced and demonstrated and demon	ducing i epth pla	t into the	e hold. I	f cement	or oth
ras placed and the method or plugs were used, state the cluster feet for each process for e	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1	in introduced and demonstrated and demon	ducing i epth pla	t into the	e hold. I	f cement	or oth
ras placed and the method or plugs were used, state the cluster feet for each process for e	methods used haracter of s plug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath	in introduced and demonstrated and demon	ducing i epth pla	t into the	e hold. I	f cement	or oth
ras placed and the method or clugs were used, state the clugs were described by the clugs were used. Filled ho 60 sacks 10 sacks plug. 3	methods used haracter of s plug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath	in introduced and demonstrated and demon	ducing i epth pla	t into the	e hold. I	f cement	or oth
ras placed and the method or clugs were used, state the clugs were described by the clugs were used. Filled ho 60 sacks 10 sacks plug. 3	methods used haracter of s plug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath	in introduced and demonstrated and demon	ducing i epth pla	t into the	e hold. I	f cement	or oth
ras placed and the method or clugs were used, state the clugs were described by the clugs were used. Filled ho 60 sacks 10 sacks plug. 3	methods used haracter of s plug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath	in introduced and demonstrated and demon	ducing i epth pla	t into the	e hold. I	f cement	or oth
ras placed and the method or clugs were used, state the clugs were described by the clugs were used. Filled ho 60 sacks 10 sacks plug. 3	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rathe. Used 50/50	mud. acks at 27 /2 sack hu ole; 2 sac Pozmix wi	ducing i epth pla	t into the ced, from	e hold. I	f cement fee	or oth
ras placed and the method or plugs were used, state the classic feet for each produced feet feet for each produced feet feet for each produced feet feet feet feet feet feet feet fe	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath le. Used 50/50	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi	ducing i epth pla	t into the ced, from_	this shee	Synt Contract	or oth
ras placed and the method or plugs were used, state the classic feet for each process for e	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath le. Used 50/50	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi	ducing i epth pla	t into the ced, from_	this shee	Synt Contract	or oth
was placed and the method or plugs were used, state the classic feet for each process for e	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath le. Used 50/50	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi	ducing i epth pla	t into the ced, from_	this shee	Synt Contract	or oth
was placed and the method or plugs were used, state the classifier for each process feet feet feet feet feet feet feet f	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rathe. Used 50/50 I description Sterling Dril	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi	ducing i epth pla	t into the ced, from al.	this shee	Synt Contract	or oth
was placed and the method or plugs were used, state the class feet for each process feet feet for each process feet feet for each process feet feet feet feet feet feet feet f	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rathe. Used 50/50 I description Sterling Dril	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi	ducing i epth pla	t into the ced, from al. BACK of D. Box 129	this shee	STATION SASSASSASSASSASSASSASSASSASSASSASSASSAS	or oth t to
rate of Plugging Contractor (If additional Mame of Plugging Contractor (TATE OFKANSAS	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath le. Used 50/50 I description Sterling Dril	in introdame and demud. acks at 27/2 sack huole; 2 sack pozmix wi	ducing i epth pla 70'; alls and cks in th 4% go sary, use any, P. (RICI (emplo	t into the ced, from al. BACK of D. Box 129 Eyee of own	this shee	Sign Company of the c	Control of the contro
was placed and the method or plugs were used, state the class feet for each process feet feet for each process feet feet for each process feet feet feet feet feet feet feet f	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath by Used 50/50 I description Sterling Dril COUNTY COUNT	mud. acks at 27/2 sack hi ole; 2 sac Pozmix wi is necess ling Compa	ducing i epth pla 70'; ills and cks in th 4% go eary, use any, P. (RICI — (emploon oath	e BACK of D. Box 129 Eyee of owr	this shee , Sterling Will ner) or (Contact I have	Sylvent fee	or oth t to
was placed and the method or plugs were used, state the classifier for each process for eac	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath by Used 50/50 I description Sterling Dril COUNTY being first detters herein	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi is necess ling Compa	ducing i epth pla 70'; 11ls and cks in th 4% go RICI (emploon oath and the	e BACK of Box 129 Eyee of owr says: The says: The says of the s	this shee , Sterling Moner) or (contains in the property of t	Sylvent fee	or oth t to
was placed and the method or plugs were used, state the classifier for each process for eac	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath by Used 50/50 I description Sterling Dril COUNTY being first detters herein	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi is necess ling Compa	ducing i epth pla 70'; 11ls and cks in th 4% go RICI (emploon oath and the	e BACK of D. Box 129 Eyee of owr	this shee , Sterling Moner) or (contains in the property of t	Sylvent fee	or oth t to
was placed and the method or plugs were used, state the classifier for each process for eac	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath b. Used 50/50 I description Sterling Dril COUNT being first ditters herein e true and co	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi is necess ling Compa	ducing i epth pla 70'; 11ls and cks in th 47 go any, P. (RICI (emploon oath and the object of the character) RICI (emploon oath and the object of the character) RICI (emploon oath and the object of the character) RICI (emploon oath and the object of the character) RICI (emploon oath and the object of the character)	e BACK of D. Box 129 Syee of owr log of the Gorilling	this shee , Sterling Michigan That I have above of COMPANY	Sylvent fee	or oth t to
was placed and the method or plugs were used, state the classifier for each process for eac	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath b. Used 50/50 I description Sterling Dril COUNT being first ditters herein e true and co	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi is necess ling Compa	epth pla 70'; 11ls and 28 in 29 th 47 go RICI (emploon oath and the object in F. A. V	e BACK of D. Box 129 Syee of owr log of the Godilling Guellner.	this shee , Sterling Miner) or (of that I have above to G COMPANY Secretary	t) Composition of the secretary of the s	or oth t to
was placed and the method or plugs were used, state the class feet for each process feet feet for each process feet feet for each process feet feet feet feet feet feet feet f	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath b. Used 50/50 I description Sterling Dril COUNT being first ditters herein e true and co	mud. acks at 27/2 sack hu ole; 2 sac Pozmix wi is necess ling Compa	epth pla 70'; 11ls and 28 in 29 th 47 go RICI (emploon oath and the object in F. A. V	e BACK of D. Box 129 Syee of owr log of the Godilling Guellner.	this shee , Sterling Miner) or (of that I have above to G COMPANY Secretary	t) Composition of the secretary of the s	or oth t to
was placed and the method or plugs were used, state the classifier for each process for each process. Filled ho 60 sacks 10 sacks plug. 3 mousehole (If additional mousehole TATE OF KANSAS F. A. Wuellner for the above-described well, the facts, statements, and mass filed and that the same are	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath by Used 50/50 I description Sterling Dril COUNTY being first ditters herein e true and co (Sig	mud. acks at 27/2 sack hu ole; 2 sack Pozmix wi is necess ling Compa Try OF uly sworn contained rrect. Sonature)	RICI (emplo on oath and the object in F. A. V	e BACK of D. Box 129 E yee of owr , says: The Gordinary , Says: T	this shee , Sterling Miner) or (of the shove-of COMPANY Secretary terling, address)	STATE OF PARTY OF THE STATE OF	or oth t to
was placed and the method or plugs were used, state the classifier for each process for eac	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath by Used 50/50 I description Sterling Dril COUNTY being first ditters herein e true and co (Sig	mud. acks at 27/2 sack hu ole; 2 sack Pozmix wi is necess ling Compa	RICI (emplo on oath and the object in F. A. V	e BACK of D. Box 129 E yee of owr , says: The Gordinary , Says: T	this shee , Sterling Miner) or (of that I have above to G COMPANY Secretary	STATE OF PARTY OF THE STATE OF	or oth t to
was placed and the method or plugs were used, state the classifier for each process for each process. Filled ho 60 sacks 10 sacks plug. 3 mousehole (If additional mousehole TATE OF KANSAS F. A. Wuellner for the above-described well, the facts, statements, and mass filed and that the same are	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath by Used 50/50 I description Sterling Dril COUNTY being first ditters herein e true and co (Sig	mud. acks at 27/2 sack hu ole; 2 sack Pozmix wi is necess ling Compa Try OF uly sworn contained rrect. Sonature)	RICI (emplo on oath and the object in F. A. V	e BACK of D. Box 129 E yee of owr , says: The Gordinary , Says: T	this shee , Sterling Miner) or (of the shove-of COMPANY Secretary terling, address)	STATE OF PARTY OF THE STATE OF	or oth t to
was placed and the method or plugs were used, state the classifier for each process for each process. Filled ho 60 sacks 10 sacks plug. 3 mousehole (If additional mousehole TATE OF KANSAS F. A. Wuellner for the above-described well, the facts, statements, and mass filed and that the same are	methods used haracter of splug set. le with heavy at 800'; 30 s at 40' with 1 sacks in rath by Used 50/50 I description Sterling Dril COUNTY being first ditters herein e true and co (Sig	mud. acks at 27/2 sack hu ole; 2 sack Pozmix wi is necess ling Compa Try OF uly sworn contained rrect. So nature) s 23rd	RICI (emplo on oath and the o hall F. A. V P. O. I	e BACK of D. Box 129 E yee of owr , says: The Gordinary , Says: T	this sheet, Sterling, W. (Chat I have above-of COMPANY Company terling) eptember	STATE OF PARTY OF THE STATE OF	or oth t to

STERLING DRILLING COMPANY P. O. Box 129 Sterling, Kansas 67579

WELL LOG - - - - - - - - WAYNE #1
Located: NE SE NW, Section 27-21S-17W, Pawnee County,
Kansas

OWNER: Beren Corporation ROTARY DRILLING CONTRACTOR: Sterling Drilling Company

COMMENCED: September 13, 1980 COMPLETED: September 20, 1980

TOTAL DEPTH: 3965'

LOG

9 - 150 Shale

150 - 790 Shale and Sand

790 - 1054 Shale

1054 - 1077 Anhydrite

1077 - 1825 Shale

1825 - 3965 Lime and Shale

CASING RECORD

Ran 20 joints 8 5/8", 23% casing. 831.96' set at 844' K.B. Cemented with 350 sacks Lite and 100 sacks 60/40 Pozmix with 2% gel and 3% cc. Plug down at 4:30 AM, 9-14-80, by Howco.

Plugged.

Deviation Surveys: 1/4° at 310' 2° at 3965'

