

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
500 INSURANCE BUILDING
212 NORTH MARKET
WICHITA, KANSAS 67202

FORM CP-1

RECEIVED
STATE CORPORATION COMMISSION
FEB 8 1972
CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Ralph Lynch

Address R.R. 4 Great Bend, Kansas

Lease (Farm Name) Code - Hutchinson Hutchinson Well No. 2

Well Location SW SW SW Sec. 35 Twp. 21 Rge. 76 (E) SW (W) SW

County Pawnee Field Name (If any) _____

Total Depth 4097 Oil Well Gas Well _____ Input Well _____ SWD Well _____ D & A _____

Was well log filed with application? yes If not, explain: _____

Date and hour plugging is desired to begin _____

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of company representative in charge of plugging operations Ralph Lynch

Casing Pulling Address R.R. 4 Great Bend

Plugging Contractor Ralph Lynch License No. 457

Address R.R. 4 Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to Ralph

Lynch Address R.R. 4 Great Bend

and payment will be guaranteed by applicant.

Signed: Ralph Lynch
Applicant or Acting Agent

Date: 2/7/72

State of Kansas



15-145-20152-0000

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian
Wichita, Kansas 67217

February 11, 1972

RECEIVED
STATE CORPORATION COMMISSION
MAR 10 1972
CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING AUTHORITY

Well No.	2
Lease	Cade-Hutcherson
Description	SW SW SW 35-21-16W
County	Pawnee
Total Depth	4097
Plugging Contractor	Co. Tools

Ralph Lynch
R. R. # 4
Great Bend, Kansas 67530

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Very truly yours,

J. Lewis Brock
J. Lewis Brock, Administrator

Mr. Leo Massey Box 582 Hays, Kansas
is hereby assigned to supervise the plugging of the above named well.