STATE OF KANSAS STATE CORPORATION COMMISSION

WELL PLUGGING RECORD

Make Required Affidavit				_		_	
		fford				PIS Rge. 11W E/W	
Mail or Deliver Report to			'CNW\sw\'	or foota	ge from li	ines	
Conservation Division		L, SW/L					
State Corporation Comm.	Lease (G. Holl		<u> </u>		
245 North Water		Lease Name Rugan "E" #2 Well No. 2					
Wichita, KS 67202	Office Charact	Address_6 er of Wel	427 East	Kellogg, leted as O	Wichita, il, Gas o	Kansas 67207 r Dry Hole)	
		Т	ry Hole				
	Date We	ell comple			Aug	ust 7., 1979 19	
				filed		st 12, 1979 19	
	Applica	tion for	plugging	approved		st 12, 1979 19	
 	Pluggin	ig commenc	ed	3:00	O PM. Augu	st 12, 1979 19	
		ng complet	eđ	4:4	5 PM. Augu	st 12, 1979 ¹⁹	
	Reason	for aband	onment o	of well or	producing	formation	
				Dry	Hole		
						last production 19	
Locale well correctly on above Section Plat						lon Division or	
				ng was co		Yes .	
Name of Conservation Agent who so							
Producing formation		oth to top			_Total Dep	oth of Well 3440'	
Show depth and thickness of all v	water, oil	and gas	formatio	ons.			
OIL, GAS OR WATER RECORDS						~! ~=	
						CASING RECORD	
FORMATION	ONTENT	. FROM	ТО	SIZE	PUT IN	. PULLED OUT	
			<u> </u>	8 5/8"	254	None	
		<u> </u>					
			 		<u> </u>		
	hods used						
was placed and the method or method plugs were used, state the chara- feet for each plug	cter of se	in introd	ucing it	into the			
was placed and the method or method plugs were used, state the character feet for each plug	cter of se	in introd	ucing it	into the		f cement or other	
was placed and the method or method plugs were used, state the character feet for each plug. Filled here	cter of se set.	in introd	ucing it	into the		f cement or other	
was placed and the method or method plugs were used, state the character feet for each plug Filled he pumped to	cter of se set. ole with h	in introd	ucing it pth place	into the ced, from_	hold, I	f cement or other feet to	
was placed and the method or method plugs were used, state the character feet for each plug Filled he Pumped to with 4%	ole with h	in introdome and de eavy mid. O.P. 40 sacot and 25 s	ucing it pth place pth pla	into the ced, from_	hold, I	f cement or other feet to	
was placed and the method or method plugs were used, state the character feet for each plug Filled he Pumped to with 1% dolid br	cter of se set. ole with h hru open I gel at 150 idge at 160	in introdome and de meavy mid. 1. P. 10 sac 1. and 25 serve with place.	cks 50/5	into the ced, from_	hold, I	f cement or other feet to	
was placed and the method or method plugs were used, state the character feet for each plug Filled he Pumped to with his solid brown hulls an	cter of se set. ole with h hru open I gel at 150 idge at 10 d 10 sacks	in introdome and de leavy mid. 1.P. 10 sac. 1. and 25 sec. 1. with plus to surface	cks 50/5	into the ced, from_	hold, I	f cement or other feet to	
was placed and the method or method plugs were used, state the character feet for each plug Filled he Pumped to with his solid brown hulls an	cter of se set. ole with h hru open I gel at 150 idge at 160	in introdome and de leavy mid. 1.P. 10 sac. 1. and 25 sec. 1. with plus to surface	cks 50/5	into the ced, from_	STATE CORPOR	f cement or other feet to AFIVED RATION COMMISSION 291070	
was placed and the method or method plugs were used, state the character feet for each plug feet for each plug Filled he Pumped to with 1% dolid brown hulls an 2 sacks	ole with h hru open I gel at 1,50 idge at 1,0 d 10 sacks in rathole	in introdome and de meavy mud. 1. P. 10 sac 1. and 25 si with plus to surface	cks 50/5	o Pozmix 240'	STATE GORPOR	f cement or other feet to REIVED RATION COMMISSION 291979	
was placed and the method or method plugs were used, state the character feet for each plug feet for each plug Filled he Pumped to with 1% dolid brown hulls an 2 sacks	ole with h hru open I gel at 1,50 idge at 1,0 d 10 sacks in rathole	in introdome and de meavy mud. 1. P. 10 sac 1. and 25 si with plus to surface	cks 50/5	o Pozmix 240'	STATE GORPOR	f cement or other feet to REIVED RATION COMMISSION 291979	
was placed and the method or method plugs were used, state the character feet for each plug Filled he Pumped to with had solid brown hulls an 2 sacks: (If additional descriptions and the sacks are sacks)	ole with h hru open I gel at 150 idge at 10 d 10 sacks in rathole	in introdome and de meavy mid. D.P. 10 sacor and 25 sor with plus to surface.	cks 50/5 sacks at 1 ce.	O Pozmix 240'	STATE REC	F cement or other feet to CEIVED RATION COMMISSION 291979	
was placed and the method or method plugs were used, state the character feet for each plug feet for each plug Filled he Pumped to with 1% dolid brown hulls an 2 sacks	ole with h hru open I gel at 150 idge at 10 d 10 sacks in rathole	in introdome and de meavy mid. D.P. 10 sacor and 25 sor with plus to surface.	cks 50/5 sacks at 1 ce.	O Pozmix 240'	STATE REC	Teet to CEIVED RATION COMMISSION 291979	
was placed and the method or method plugs were used, state the character feet for each plug Filled he Pumped to with has solid brown hulls an 2 sacks:	ole with h hru open I gel at 150 idge at 10 d 10 sacks in rathole	in introdome and de meavy mid. D.P. 10 sacor and 25 sor with plus to surface.	cks 50/5 sacks at 1 ce.	O Pozmix 240'	STATE REC	F cement or other feet to CEIVED RATION COMMISSION 291979	
was placed and the method or method plugs were used, state the character feet for each plug Filled he Pumped to with had solid brown hulls an 2 sacks: (If additional descriptions and the sacks are sacks)	ole with h hru open I gel at 150 idge at 140 d 10 sacks in rathole scription rling Dril	in introdome and de meavy mid. D.P. 10 sacor and 25 sor with plus to surface.	cks 50/5 sacks at 1 ce.	O Pozmix 2h0' / L sack BACK of D. Box 129	STATE RECORPOR	F cement or other feet to CEIVED RATION COMMISSION 291979	
was placed and the method or method plugs were used, state the character feet for each plug Filled here with has solid brown hulls and 2 sacks: (If additional desemble of Plugging Contractor Steelers of Kansas F. A. Whellper	ole with h hru open I gel at 150 idge at 140 d 10 sacks in rathole scription rling Dril	in introdome and de meavy mid. P. 10 sac of and 25 so with plus to surface is necessaling Company of the compa	cks 50/5 sacks at a g and 1 ce. RICO	O Pozmix 240' /4 sack BACK of D. Box 129	STATE RECORPORE GUNSERVALUE this SWeet , Sterling	Fiven feet to CEIVED PATION COMMISSION 291979 Nones See Kansas 67579 ss.	
was placed and the method or methor plugs were used, state the character feet for each plug feet for each plug Filled he Pumped the with 1% dolid brown hulls an 2 sacks: (If additional des Name of Plugging Contractor Stemman State of the above-described well, being the facts, statements, and matter	ole with he hru open I gel at 150 idge at 140 d 10 sacks in rathole scription rling Dril	in introdome and de meavy mud. De 10 sac 10	eks 50/5 sacks at ag and 1 ce. RICI (employon oath and the help me STERLING)	O Pozmix 2h0' /4 sack BACK of D. Box 129 E yee of own says: T log of the God. DRILLING	STATE RECORPORE GUNSERVALUE this SWEET this Sterling er) or (or hat I have e above—de	FIVED RATION COMMISSION 291979 Notice Signature S. Kansas 67579 ss. wher or operator) e knowledge of	
was placed and the method or methor plugs were used, state the character feet for each plug feet for each plug Filled he Pumped the with 1% dolid brown hulls an 2 sacks: (If additional des Name of Plugging Contractor Stemman State of the above-described well, being the facts, statements, and matter	ole with he hru open I gel at 150 idge at 140 d 10 sacks in rathole scription rling Dril	in introdome and de meavy mid. P. 10 sac. and 25 services in the place of the surface of the s	eks 50/5 eks 50/5 eacks at a and 1 ce. RICI (employon oath and the help me STERLING)	Description of the sed, from 240' BACK of D. Box 129 E yee of own, says: T log of the God. BORILLING	STATE RECORPORE GONSERVALUE this SWeet , Sterling er) or (or hat I have e above—de COMPANY ecretary	SEIVED RAHON COMMISSION 29 1979 Nonsas g. Kansas 67579 ss. wher or operator) e knowledge of escribed well	
was placed and the method or methor plugs were used, state the character feet for each plug feet for each plug Filled he Pumped the with 1% dolid brown hulls an 2 sacks: (If additional des Name of Plugging Contractor Steeperson State of Kansas	cter of se set. cole with here open I gel at 150 idge at 100 d 10 sacks in rathole scription rling Dril COUNT g first dus herein due and con (Sign	in introdome and define and define and 25 solvent plus to surface is necessaling Company of the contained crect. Solvent in the contained crect.	eks 50/5 eks 50/5 eacks at a and 1 ce. RICI (employon oath and the help me STERLING)	Description of the ced, from one of the ced, from one of the ced o	COMPANY COM	SEIVED RATION COMMISSION 29 1979 Ransas 67579 ss. where or operator) e knowledge of escribed well ansas 67579	
was placed and the method or methology plugs were used, state the character feet for each plug. Filled he Pumped to with 1% dolid brown hulls and 2 sacks: (If additional des Name of Plugging Contractor Stepped STATE OF KANSAS F. A. Whellner of the above-described well, being the facts, statements, and matter as filed and that the same are transfer of the same are tr	cter of se set. cole with here open I gel at 150 idge at 100 d 10 sacks in rathole scription rling Dril COUNT g first dus herein due and con (Sign	in introdome and de meavy mud. De you mud.	cks 50/5 sacks at a g and 1 ce. RICI (employon oath and the help me STERLING) F. A. W. F. A. W. P. O. B.	Description of the ced, from one of the ced, from one of the ced o	STATE RECORPORE GONSERVALUE this SWeet , Sterling er) or (or hat I have e above—de COMPANY ecretary	SEIVED RAHON COMMISSION 29 1979 Nonsas g. Kansas 67579 ss. wher or operator) e knowledge of escribed well	
was placed and the method or methor plugs were used, state the character feet for each plug feet for each plug feet for each plug with 1% dolid brown hulls and 2 sacks (If additional des Name of Plugging Contractor Stemman State of the above-described well, being the facts, statements, and matter as filed and that the same are transfer of the	cter of se set. cole with here open I gel at 150 idge at 100 d 10 sacks in rathole scription rling Dril COUNT g first dus herein due and con (Sign	in introdome and de meavy mid. P. 10 sac. I and 25 services and 25 services. Is necessaling Compared from the contained frect. Soc. 15th	eks 50/5 sacks at ag and 1 ce. RICI (employon oath and the help me STERLING) F. A. Wi	Description of the ced, from one of the ced, from one of the ced o	STATE RECORPORE CONSERVATOR this SWeet this Sweet this Sweet company	SEIVED RATION COMMISSION 29 1979 Ransas 67579 ss. where or operator) e knowledge of escribed well ansas 67579	

P. O. Box 129 Sterling, Kansac 67579

Located: C SL, SW/L, Section 2-210-110, Stafford County, lancas

CMYTR: P. C. Voll ROTARY RELALIC COMPRESSOR: Sterling Drilling Company

00 | 10000: August 7, 1979 00000 WW: August 12, 1979

COTAL DIFTY: 3hlo:

Las

0 - 150 Sand

-150 - 256 Shale

256 - 1050 Red Red and Salt Thale

1050 - 3285 Lime and -hale

3285 - 3375 Line, Lhale, Chert

3375 - 3hhO Lime, Chale, Lond

CAFLEGO MICCORD

Ran 7 joints used 284, 8 5/8" casing, 2h1.69' set at 254' K.B. with 225 sacks 60/40 Formix with 37 cc. "lug down at 11:00 FM, 8-7-79, by Howco.

Plugged.

STATE CORPORATION COMMISSION

AUG 2 9 1979

CONSERVATION DIVISION Wichita, Kansas