

15-159-00092-00-01

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
800 BITTING BUILDING  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Branine & Holl Address 822 Central Bldg.  
(Applicant) Wichita 2, Kansas

Lease (Farm Name) Dresbach Well No. #2

Well Location SW NE Sec. 7 Twp. 21 Rge. 6 (E)-(W) W

County Rice Field Name (if any) Wurry West

Total Depth 3543 Oil Gas Dry Hole dry hole

Was well log filed with application? no. If not, explain: \_\_\_\_\_

Reopened Old hole

Date and hour plugging is desired to begin 12-20-53

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.

(Use an additional sheet if necessary) \_\_\_\_\_

Name of the person on the lease in charge of well for owner J. S. Cling

Box 326 Address McPherson, Kansas

Name of Plugging Contractor The McPherson Oil Company Under

supervision of Ruel Durkee  
Address Box 326, McPherson, Kansas

Invoice covering assessment for plugging this well should be sent to

Branine & Holl Address 822 Central Bldg.  
Wichita 2, Kansas

and payment will be guaranteed by applicant.

**PLUGGING**  
FILE SEC 7 T 21 R 6W  
BOOK PAGE 3 LINE 3

J. S. Cling  
Applicant or Acting Agent

Date 12-21-53

12-22-1953



STATE OF KANSAS  
 STATE CORPORATION COMMISSION  
 CONSERVATION DIVISION  
 800 BITTING BUILDING  
 WICHITA, KANSAS

December 22, 1953

Well No.	2
Lease	Drestach
Description	SW 1/4 7-21-6W
County	Rice
File No.	3-3

Branine & Holl  
 822 Central Bldg.  
 Wichita, Kans.

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Ruol Durken, Box 597, McPherson, Kansas.

STATE CORPORATION COMMISSION  
 CONSERVATION DIVISION

BY: J. P. Roberts  
 J. P. ROBERTS

cc: District Plugging Supervisor