٠,

INV. NO.

T,o:	•	API NUMBER 13=
STATE CORF	PORATION COMMISSION	API NUMBER 15- 185-22,376.000
	ION DIVISION - PLUGGING SECTION ADO DERBY BUILDING	
WICHITA, K	CANSAS 67202	4950 feet from \$ section 11
	I'S PLUGGING REPORT	990 feet from E section II
Operator l	icense # 5122	Lease Name Langer Well 2
	Woodman-Jannitti Drilling Co.	County Stafford 115
Name& Address	P. O. Box 308	Well Total Depth 3567 Arbuckle 7' fe
	Great Bend, KS 67530	Conductor Pipe: Sizefeet
		Surface Casing: Size 8 5/8 feet 809
Abandoned	OIL Well Gas Well	Input Well D&A
•		
;		illing Co. License Number 5122
	P. O. Box 308, Great Bend, KS 6	
Company to	plug at: Hour: 9:30 am Day:	3 Month: July Year:19 86
Plugging p	proposal received from	Rîch Wheeler
(company г	wame) Woodman-Tannitti	(phone) 316-792-1922
		Elevation 1920 cement through drill pipe Anhydrite N/A
	30' below the base of the surfac at 300' with 25 sx cement	ce pipe with 50 sx cement
3rd plug	from 40' to surface with 10 sx o	cement_
4th plug t	to administration to be to substitute of	k cement
	to circulate rat hole with 15 sx	Cr. Comont
	to circulate mouse hole with 10	pposal Received by Richard W. Lacey
	to circulate mouse hole with 10	
5th plug 1	to circulate mouse hole with 10	pposal Received by Richard W. Lacey (TECHNICIAN)
Sth plug (Plugging Pro Properations attended by Agent?:	pposal Received by Richard W. Lacey (TECHNICIAN)
Plugging (Plugging Pro Propositions attended by Agent?: Completed: Hour: 11:00 amDay:	All X Part None
Plugging (Operations	Plugging Pro Operations attended by Agent?: Completed: Hour: 11:00 amDay:	Poposal Received by Richard W. Lacey (TECHNICIAN) All X Part None 3 Month: July Year:19 86 with 50 sx cement, 2nd plug at 300' with 25 sx
Plugging (Operations ACTUAL PLUcement, 3	Plugging Pro Operations attended by Agent?: Completed: Hour: 11:00 amDay: GGING REPORT 1st plug at 850' rd plug from 40' to surface with	Posal Received by Richard W. Lacey (TECHNICIAN) All X Part None 3 Month: July Year:19 86 with 50 sx cement, 2nd plug at 300' with 25 sx 1 15 sx cement, 4th plug to circulate rat hole
Plugging (Operations ACTUAL PLUcement, 3) with 15 so	Plugging Properations attended by Agent?: Completed: Hour: 11:00 amDay: CGGING REPORT 1st plug at 850' Cd plug from 40' to surface with ck cement, 5th plug to circulate	Poposal Received by Richard W. Lacey (TECHNICIAN) All X Part None 3 Month: July Year:19 86 with 50 sx cement, 2nd plug at 300' with 25 sx
Plugging (Operations ACTUAL PLUcement, 3) with 15 so	Departions attended by Agent?: Completed: Hour: 11:00 amDay: CGGING REPORT 1st plug at 850' and plug from 40' to surface with coment, 5th plug to circulate	Posal Received by Richard W. Lacey (TECHNICIAN) All X Part None 3 Month: July Year:19 86 with 50 sx cement, 2nd plug at 300' with 25 sx 1 15 sx cement, 4th plug to circulate rat hole
Plugging (Operations ACTUAL PLUcement, 3) with 15 so	Departions attended by Agent?: Completed: Hour: 11:00 amDay: CGGING REPORT 1st plug at 850' and plug from 40' to surface with coment, 5th plug to circulate	Posal Received by Richard W. Lacey (TECHNICIAN) All X Part None 3 Month: July Year:19 86 with 50 sx cement, 2nd plug at 300' with 25 sx 15 sx cement, 4th plug to circulate rat hole mouse hole with 10 sx cement. Circulated
Plugging (Operations ACTUAL PLUcement, 3) with 15 so	Departions attended by Agent?: Completed: Hour: 11:00 amDay: CGGING REPORT 1st plug at 850' and plug from 40' to surface with coment, 5th plug to circulate	Richard W. Lacey (TECHNICIAN) All X Part None 3 Month: July Year:19 86 with 50 sx cement, 2nd plug at 300' with 25 sx 15 sx cement, 4th plug to circulate rat hole mouse hole with 10 sx cement. Circulated
Plugging (Operations ACTUAL PLUcement, 31 with 15 so	Departions attended by Agent?: Completed: Hour: 11:00 amDay: CGING REPORT 1st plug at 850' Cd plug from 40' to surface with Ex cement, 5th plug to circulate the water well. Used 60/40 Pozmix 6% gel by BJ-T	All X Part None Sample None No
Plugging (Operations ACTUAL PLUcement, 31 with 15 sa	Departions attended by Agent?: Completed: Hour: 11:00 amDay: CGING REPORT 1st plug at 850' Cd plug from 40' to surface with cement, 5th plug to circulate the water well. Used 60/40 Pozmix 6% gel by BJ-T (If additional description is	All X Part None Sample None No
Plugging (Operations ACTUAL PLUcement, 3) with 15 somethin Remarks: [Departions attended by Agent?: S Completed: Hour: 11:00 amDay: GGING REPORT 1st plug at 850' End plug from 40' to surface with K cement, 5th plug to circulate the water well. Used 60/40 Pozmix 6% gel by BJ-T (if additional description i	All X Part None S Month: July Year:19 86 with 50 sx cement, 2nd plug at 300' with 25 sx at 15 sx cement, 4th plug to circulate rat hole mouse hole with 10 sx cement. Circulated Citan Is necessary, use BACK of this form.)

CONSERVATION DIVISION-

FORM CP-2/3 Rev.01-84