

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

Lease Owner S. A. Yarnell Address 1009 E. Douglas Wichita 7, Kansas.
(Applicant)

Lease (Farm Name) Spacil Well No. 5

Well Location NW NW NE Sec. 4 Twp. 21 Rge. 12 (E)-(W) W

County Stafford Field Name (if any) _____

Total Depth 3431 Oil Gas Dry Hole Production Exhausted

Was well log filed with application? . If not, explain: _____

Well log was filled on completion of well

Date and hour plugging is desired to begin Aug. 27 to Sept. 2, 1953

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.
(Use an additional sheet if necessary) _____

Name of the person on the lease in charge of well for owner _____

L. D. Davis Address Hudson, Kansas

Name of Plugging Contractor Pipe Pulling, Inc.

Address Stafford, Kansas.

Invoice covering assessment for plugging this well should be sent to
S. A. Yarnell Address 1009 E. Douglas, Wichita 7, Kansas.

and payment will be guaranteed by applicant.

PLUGGING
FILE SEC. 4 T. 21 R. 12W
BOOK PAGE 122 LINE 26

AUG 1 1953
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
WICHITA, KANSAS

S. A. Yarnell
Applicant or Acting Agent

Date Aug. 18, 1953

8-19-1953



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 800 BITTING BUILDING
 WICHITA, KANSAS

August 19, 1953

Well No.	5
Lease	Spacil
Description	NW NW SEC 1-21-12W
County	Stafford
File No.	122-26

Mr. S.A. Yarnell
 1009 E. Douglas
 Wichita 7, Kansas

Dear Sir:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 118, Pratt, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

BY: J. P. Roberts
 J. P. ROBERTS

cc: District Plugging Supervisor