

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Murfin & Aurora Address Union Nat. Bank Bldg - Wichita, Ks.  
(Applicant)

Lease (Farm Name) Alexander Well No. 1

Well Location NE NE NE Sec. 31 Twp. 20 Rge. 19W(E) - (W)

County Pawnee Field Name (if any) -

Total Depth 4753 Oil Gas Dry Hole xxxxx

Was well log filed with application? yes If not, explain: \_\_\_\_\_

Date and hour plugging is desired to begin March 7, 1956

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner Bill Brown

219 S. Windsor Address Russell, Kansas

Plugging Contractor Murfin Drilling Company

Plugging Contractor's License No. \_\_\_\_\_

Address 507 Union Nat. Bank Bldg - Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to \_\_\_\_\_

Murfin Drilling Co. Address same as above

and payment will be guaranteed by applicant.

RECEIVED  
STATE CORPORATION COMMISSION

*WR Murfin*

Applicant or Acting Agent

APR 4 - 1956

44-56  
CONSERVATION DIVISION  
Wichita, Kansas

Date March 9, 1956

**PLUGGING**  
FILE SEC 31 T 20 R 19W  
BOOK PAGE 44 LINE 43



15.145.00130.0000

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS  
March 12, 1956

Well No.	1
Lease	Alexander
Description	NE NE NE 31-20-19W
County	Pawnee
File No.	44-43

Aurora Gasoline Company  
304 Union National Bank Bldg.,  
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. M. Brundage, Box 283, Hoisington, Kansas.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

By S. S. Greider  
S. S. Greider  
WELL PLUGGING SUPERVISOR

cc:  
District Plugging Supervisor