STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
212 North Market, Insurance Bldg



WELL PLUGGING RECORD

212 North Market, Insurance Bldg. Wichita, Kansas		Pawnee	County		wp 11gc	\ \ <i>E\-</i> \		
north		IE/CNW#SW#"	or indicable item	11 11HO3		$\frac{16}{E}$ (E) $\frac{W}{W}$		
· · ·	Lease Owner	~ 1	ern & S	pecter,				
	Lease Name	<u>Osborne</u>	T/ n m m n m			. Well No \		
		Russell,						
		Character of Well (completed as Oil, Gas or Dry Hole)						
	Date well com	Date well completed 2-4-56 19 Application for plugging filed 1-24-61 19						
	Application to	r plugging filed	1-54.	<u>-01</u> 41		19		
	Application for	r plugging approv	2-21 - 61	<u>-01</u>				
		11011000	2-23-61					
i <u>_l</u> i	Plugging comp			. De	nleted.	19		
	Reason for aba	andonment of wel	l or producing	formation DC	DICOCKE			
	TEdu sino		-1 J.LC 1			10		
	1			_		19_ ore plugging was o		
Locate well correctly on above Section Plat	menced?		the Conserva	idon Division o.	i its agents bero	ne plugging was t		
me of Conservation Agent who s			ank Bros	adfoot				
ducing formation Arbuck	le	Depth to top 3	811 Bottom	3842	Total Depth of	Well 3842		
w depth and thickness of all wa			Dottoin.		rotar Dopth of	***************************************		
w depth and thickness of an wa	tor, on and gas roamand	52.5°						
OIL, GAS OR WATER RECO	RDS		· · · · · · · · · · · · · · · · · · ·	 		CASING RECOR		
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED DUT		
				8-5/8"	986*	None		
				5-1/2"	3841号	3119		
	_	 		-	~			
		,						
			 -					
Describe in detail the manner introducing it into the hole. If feet for each plug	cement or other plugs vg set. Checked ho	were used, state t	he character o	f same and dept	h placed, from	f		
introducing it into the hole. If	cement or other plugs vg set. Checked ho dumped 5 s bailer. Filled sur	le to 384 acks of c	2°, ran ement @ EXE Pu with 4	sand to 3830' willed 52" 0 barrel:	3830° an ith dump casing.	nd		
introducing it into the hole. If	Checked ho	le to 384 acks of c	2°, ran ement @ EXE Pu with 4	sand to 3830' willed 52" 0 barrel:	3830° an ith dump casing.	nd		
introducing it into the hole. If	cement or other plugs vg set. Checked ho dumped 5 s bailer. Filled sur	le to 384 acks of c	2°, ran ement @ EXE Pu with 4	sand to 3830' willed 52" 0 barrel:	3830° an ith dump casing.	nd		
introducing it into the hole. If	Checked ho dumped 5 s bailer. Filled sur and pumped	le to 384 acks of c XENHENXAN face pipe in 80 sa	2°, ran ement @ EXE Pu with 4	sand to 3830' willed 52" 0 barrel:	3830° an ith dump casing.	nd		
introducing it into the hole. If	cement or other plugs vg set. Checked ho dumped 5 s bailer. Filled sur	le to 384 acks of c XENHENXAN face pipe in 80 sa	2°, ran ement @ EXE Pu with 4	sand to 3830' willed 52" 0 barrel:	3830° an ith dump casing.	nd		
introducing it into the hole. If	Checked ho dumped 5 s bailer. Filled sur and pumped	le to 384 acks of c XENHENXAN face pipe in 80 sa	2°, ran ement @ EXE Pu with 4	sand to 3830' willed 52" 0 barrels cement to	3830° an ith dump casing. s of mud	nd		
introducing it into the hole. If	Checked ho dumped 5 s bailer. Filled sur and pumped	le to 384 acks of c XENHENXAN face pipe in 80 sa	2°, ran ement @ KXX Pu with 4 cks of	sand to 3830' willed 52" 0 barrels cement to	3830° and the dump casing. Sof mud of surface	nd		
introducing it into the hole. If	Checked ho dumped 5 s bailer. Filled sur and pumped	le to 384 acks of c XENHENXAN face pipe in 80 sa	2°, ran ement @ KXX Pu with 4 cks of	sand to sand to 3830' wi 11ed 52" 0 barrels cement to	3830 and the dump casing. sof mud of surface	nd		
introducing it into the hole. If	Checked ho dumped 5 s bailer. Filled sur and pumped	le to 384 acks of c XENHENXAN face pipe in 80 sa	2°, ran ement @ KXX Pu with 4 cks of	sand to 3830' willed 52" 0 barrels cement to	3830 and the dump casing. sof mud of surface	nd		
introducing it into the hole. If	Checked ho dumped 5 s bailer. E Filled sur and pumped	le to 384 acks of c XEANKAXAN face pipe in 80 sa	2°, ran ement @ XXX Pu with 4 cks of	sand to 3830' wi 11ed 52" 0 barrels conrolation Wichita, Nar	3830 and the dump casing. sof mud of surface	nd		
introducing it into the hole. Iffeet for each plus	Checked ho dumped 5 s bailer. E Filled sur and pumped PLUGGING C	le to 384 acks of c XENKAXAN face pipe in 80 sa	2°, ran ement @ XXX Pu with 4 cks of	sand to 3830' wi 11ed 52" 0 barrels conrolation Wichita, Nar	3830 and the dump casing. sof mud of surface	nd		
introducing it into the hole. Iffeet for each plug	Checked ho dumped 5 s bailer. E Filled sur and pumped	le to 384 acks of c XENKAXAN face pipe in 80 sa	2°, ran ement @ XXX Pu with 4 cks of	sand to 3830' wi 11ed 52" 0 barrels conrolation Wichita, Nar	3830 and the dump casing. sof mud of surface	nd		
introducing it into the hole. Iffeet for each plug ame of Plugging Contractor	Checked ho dumped 5 s bailer. E Filled sur and pumped PLUGGING C	le to 384 acks of c XENKAXAN face pipe in 80 sa	2°, ran ement @ XXX Pu with 4 cks of	sand to 3830' wi 11ed 52" 0 barrels conrolation Wichita, Nar	3830 and the dump casing. sof mud of surface	nd		
introducing it into the hole. If	Checked ho dumped 5 s bailer. E Filled sur and pumped	le to 384 acks of c XEANKAXAN face pipe in 80 sa	2°, ran ement @ XXX Pu with 4 cks of	sand to 3830' wi 11ed 52" 0 barrels conrolation Wichita, Nar	3830 and the dump casing. sof mud of surface	nd		
introducing it into the hole. If	Checked ho dumped 5 s bailer. E Filled sur and pumped PLUGGING C	le to 384 acks of c XENKAXAN face pipe in 80 sa	2°, ran ement @ XXX Pu with 4 cks of	sand to 3830' wi 11ed 52" 0 barrels conrolation Wichita, Nar	3830 and the dump casing. sof mud of surface	nd .		
Introducing it into the hole. Iffeet for each plus	Checked ho dumped 5 s bailer. M Filled sur and pumped PLUGGING C KNIGHT CAS CHASE, KAN	le to 384 acks of c leaks of c le	essary, use BACK.	sand to 3830' willed 52" 0 barrels eement to COMPONATION Wichita, Nat	3830 and the dump casing. sof mud of surface. DIVISION SESS.	of the above-des		
Introducing it into the hole. Iffeet for each plug Jame of Plugging Contractorddress TATE OFvell, being first duly sworn on oa	Checked ho dumped 5 s bailer. E Filled sur and pumped PLUGGING C KNIGHT CAS CHASE, KAN KANSAS CO Noel J. Kr	le to 384 acks of c AEMARAXAM face pipe in 80 sa COMPLETE.	2, ran ement @ KXK Pu With 4 cks of State CON STATE (employee of e facts, statem	sand to 3830' willed 52" 0 barrels cement to Wichita har Vof this sheet) owner) or (fixilates, and matter	3830 and the dump casing. sof mud of surface. DIVISION SESS.	of the above-des		
Introducing it into the hole. Iffeet for each plus	Checked ho dumped 5 s bailer. E Filled sur and pumped PLUGGING C KNIGHT CAS CHASE, KAN KANSAS CO Noel J. Kr	le to 384 acks of c AEMARAXAM face pipe in 80 sa COMPLETE.	2, ran ement @ KXK Pu With 4 cks of State CON STATE (employee of e facts, statem	sand to 3830' willed 52" 0 barrels component to Wichita, war Wichita, war Kof this sheet) owner) or (now ents, and matte	3830° and the dump casing. Sof mud of surface Division Di	of the above-desined and the log		
introducing it into the hole. Iffeet for each plugfeet for	Checked ho dumped 5 s bailer. E Filled sur and pumped PLUGGING C KNIGHT CAS CHASE, KAN KANSAS CO Noel J. Kr	le to 384 acks of c kenkenxam face pipe in 80 sa complete. comple	2, ran ement @ KXK Pu With 4 cks of State CON STATE (employee of e facts, statem	sand to 3830 willed 52 of barrels controlled 52 of this sheet) owner) or (now ents, and matter) Chas	3830 and the dump casing. sof mud of surface. DIVISION SESS.	of the above-desined and the log		
ame of Plugging Contractor	Checked ho dumped 5 s bailer. E Filled sur and pumped PLUGGING C KNIGHT CAS CHASE, KAN KANSAS Noel J. Kr	le to 384 acks of c kenkenxam face pipe in 80 sa complete. comple	essary, use BACF. No.	sand to 3830 willed 52 of barrels cement to Conformation Wichita, nor Cof this sheet) owner) or (now ents, and matte	3830° and the dump casing. Sof mud bourface Division Division ass. See See See See See See See See See Se	of the above-desined and the log		
introducing it into the hole. Iffeet for each plugging contractorddress	Checked ho dumped 5 s bailer. E Filled sur and pumped PLUGGING C KNIGHT CAS CHASE, KAN KANSAS Noel J. Kr	le to 384 acks of c AEAMMAXAM face pipe in 80 sa COMPLETE. The property of the sand correct. So (Signature)	essary, use BACF. No.	sand to 3830' willed 52" 0 barrels cement to COMPONATION Wichita, Nar Cofthis sheet) owner) or (now ents, and matte	3830° and the dump casing. Sof mud bourface Division Division ass. See See See See See See See See See Se	of the above-desined and the log		

WELL LOG BUREAU-KANSAS GEOLOGICAL SOCIETY

2500

3550

3835

3841 3842

508 East Murdock,

Wichita, Kansas

Company- ROCKET DRILLING CO., INC. Farm-Osbourn No. 1

SEC. 33 21 R. 16W NW SW SE

Total Depth. 3842. Comm. 1-26-56

Comp. 2-4-56

Shot or Treated.

Contractor. Rocket Drilling; Co., Inc. Issued. 4-28-56

lime

lime

lime & shale

conglomerate

Arbuckle Total Depth

lime & conglomerate

CASING:

8 5/8 986' w/ 450 sx cmt. 5 1/2 3841.5' w/ 120 sx cmt.

County Pawnee KANSAS

Elegation. 1996 RB

Preduction, 200 BOPD

	Figures It. leate Pottom of Formations
sand	100
shale	330
sand	345
shale	415
Dakota sand	515
red shale	555
shale	979
anhydrite	1005
shale & shells	1475
shale	1905
shale & lime	2025
lime	2075
sand	2080
lime & shale	2175
sand	2190
lime & shale	2355
lime	2410
sand	2425
	'T'-' /

TOPS:	. ***	ي سوسه يه الهيد	erre rize si pr
Heebner	-		3395
Brown lime			3495
Lansing —			3503
Arbuckle			3841