

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Musgrove Petroleum Corp. Address 518 Petroleum Building
(Applicant) Wichita, Kansas.
Lease (Farm Name) EDWARDS Well No. 1
Well Location NE NE NE Sec. 26 Twp. 20 Rge. (E) 19 (W)
County Pawnee Field Name (if any) _____
Total Depth 4500' Oil Gas Dry Hole Dry
Was well log filed with application? Yes If not, explain: _____

Date and hour plugging is desired to begin July 26, 1955
Plugging of the well will be done in accordance with the Rules and Regulations
of the State Corporation Commission.

Name of the person on the lease in charge of well for owner R. W. Peters
P. O. Box 171 Address Liberal, Kansas

Plugging Contractor Musgrove Petroleum Corporation
Plugging Contractor's License No. _____
Address 518 Petroleum Building, Wichita, Kansas.

Invoice covering assessment for plugging this well should be sent to _____
Musgrove Petroleum Corporation Address 518 Petroleum Bldg.,
Wichita, Ks.
and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION
AUG 2 X 1955
CONSERVATION DIVISION
Wichita, Kansas

Lawson J. Halling
Applicant or Acting Agent

Date July 29, 1955
PLUGGING
FILE SEC 26 TWP 20 R 19W
BOOK PAGE 138 LINE 17



15-145.00322-0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA 2, KANSAS

211 N. Broadway

July 28, 1955

Well No.	1
Lease	Edwards
Description	NE NE NE 26-20-19W
County	Pawnee
File No.	138-17

Musgrove Petroleum Corp.
518 Petroleum Building
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Warren H. Horner, Box 207, Great Bend, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY:

S. S. Greider

S. S. Greider

WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor