

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner M. B. Armer Address 710 Petroleum Bldg.
Wichita 2, Kansas
(Applicant)

Lease (Farm Name) Kitch Well No. 1

Well Location SW SW SE/4 Sec. 4 Twp. 20 Rge. (E)-(W) 19

County Pawnee Field Name (if any) Oro

Total Depth 4308 Oil Gas Dry Hole dry

Was well log filed with application? No. If not, explain: dry

Filing with Well Plugging Record

Date and hour plugging is desired to begin May 16, 1953

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.

(Use an additional sheet if necessary) _____

Name of the person on the lease in charge of well for owner _____

Roy Hardy Address Wichita, Kansas

Name of Plugging Contractor M. B. Armer

Address Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____

M. B. Armer Address Wichita, Kansas

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

MAY 21 1953

CONSERVATION DIVISION
Wichita, Kansas

[Signature]
Applicant or Acting Agent

Date 5/20/53

PLUGGING
FILE SEC 4 T 20 R 19W
BOOK PAGE 101 LINE 45



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 800 BITTING BUILDING
 WICHITA, KANSAS

May 18, 1953

| | |
|-------------|-------------------|
| Well No. | 1 |
| Lease | Kitch |
| Description | SW SW SE 4-20-19W |
| County | Pawnee |
| File No. | 101-45 |

M. B. Armer,
 710 Petroleum Bldg.,
 Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 148, Pratt, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

By J. P. Roberts
 J. P. Roberts

cc: DISTRICT PLUGGING SUPERVISOR