To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202		API NUMBER 19-145-21,190 C W/2 NW, SEC. 29 , T	
		3960 feet fi	om Section 11
TECHNICI/	AN'S PLUGGING REPORT	4620 foet fi	om Esection lir
Operator	License # 5088	Lease Name Saxton	Weil # 1
	John J. Darrah, Jr.	County Pawnee	
Name& Address	412 E. Douglas, Suite One	Well Total Depth4	500
	Wichita, KS 67202	Conductor Pipo: Size	
		Surface Casing: Size 8	
Abandone.	1 Oli Woll X Gas Well	 -	
			'
	ii as hereinafter indicated		
Plugging	Contractor Rockhold Engineerin	License	Number5111
Address_	Box 698, Great Bend, KS 67530		
Company 1	to plug at: Hour: 10:30 a.m. Day:	14 Months 5	Year:19 91
Plugging	proposal received fromJim_Roc	khold	
_	name) Rockhold Engineering		316-792-2506
	'at 4500' w/350 sx cement, PBTE		101187
	sand back to 4250' and dump 5 sx	· · · · · · · · · · · · · · · · · · ·	h hailar
TOC PIG		. Cement on top or sand throug	n parrer,
	pump 3 sx hulls, 10 sx gel, 50 s		1s, release 8 5/8"
			ls, release 8 5/8"
	pump 3 sx hulls, 10 sx gel, 50 s		ls, release 8 5/8"
	pump 3 sx hulls, 10 sx gel, 50 s ig and pump 150 sx cement.	x cement, 10 sx ge1, 1 sx hul	
	pump 3 sx hulls, 10 sx gel, 50 s ig and pump 150 sx cement.	x cement, 10 sx ge1, 1 sx hul	
wiper plu	pump 3 sx hulls, 10 sx gel, 50 s ig and pump 150 sx cement.	x cement, 10 sx ge1, 1 sx hul	d Lacey FECHNICIAN)
wiper plu	pump 3 sx hulls, 10 sx gel, 50 s ig and pump 150 sx cement. Plugging Pro	x cement, 10 sx gel, 1 sx hul posal Received by Richar (1) Ali X Part	d Lacey FECHNICIAN)
Plugging Operation	pump 3 sx hulls, 10 sx gel, 50 s ig and pump 150 sx cement. Plugging Pro Operations attended by Agent?:	x cement, 10 sx ge1, 1 sx hul posal Rocelved by Richar Ali X Part 14 Month: 5	d Lacey FECHNICIAN) None Year: 19 91
Piugging Operation	pump 3 sx hulls, 10 sx gel, 50 s Ig and pump 150 sx cement. Plugging Pro Operations attended by Agent?: Ins Completed: Hour: 11:30 a.mpay: LUGGING REPORT 1st plug sanded b	x cement, 10 sx ge1, 1 sx hul posal Rocelved by Richar Ali X Part 14 Month: 5	d Lacey FECHNICIAN) None Year: 19 91
Piugging Operation ACTUAL Pi	pump 3 sx hulls, 10 sx gel, 50 s Ig and pump 150 sx cement. Plugging Pro Operations attended by Agent?: Ins Completed: Hour: 11:30 a.mDay: LUGGING REPORT 1st plug sanded bough bailer,	x cement, 10 sx ge1, 1 sx hul posal Received by Richar Ali X Part	d Lacey FECHNICIAN) None Year: 19 91 cement on top of
Plugging Operation ACTUAL Plugand thro	pump 3 sx hulls, 10 sx gel, 50 s Ig and pump 150 sx cement. Plugging Pro Operations attended by Agent?: Ins Completed: Hour:11:30 a.mDay: LUGGING REPORT 1st plug sanded bough bailer, pumped 300 lbs. hulls, 10 sx gel	x cement, 10 sx ge1, 1 sx hul posal Received by Richar Ali X Part	d Lacey FECHNICIAN) None Year: 19 91 cement on top of
Piugging Operation ACTUAL Pi sand thro 2nd plug and 150 s	pump 3 sx hulls, 10 sx gel, 50 s Ig and pump 150 sx cement. Plugging Pro Operations attended by Agent?: Ins Completed: Hour:11:30 a.mDay: LUGGING REPORT 1st plug sanded b Dugh bailer, pumped 300 lbs. hulls, 10 sx gel Ex cement down 8 5/8".	All X Part 5 ack to 4250' and dumped 5 sx , 50 sx cement, 10 sx ge1, 10	d Lacey FECHNICIAN) None Year: 19 91 cement on top of
Plugging Operation ACTUAL Plugand thro 2nd plug and 150 s	pump 3 sx hulls, 10 sx gel, 50 s Ig and pump 150 sx cement. Plugging Pro Operations attended by Agent?: Ins Completed: Hour:11:30 a.mDay: LUGGING REPORT 1st plug sanded bough bailer, pumped 300 lbs. hulls, 10 sx gel	All X Part 5 ack to 4250' and dumped 5 sx , 50 sx cement, 10 sx ge1, 10	d Lacey FECHNICIAN) None Year: 19 91 cement on top of
Plugging Operation ACTUAL Plug and thro 2nd plug and 150 s Maximum p	pump 3 sx hulls, 10 sx gel, 50 s Ig and pump 150 sx cement. Plugging Pro Operations attended by Agent?: Ins Completed: Hour:11:30 a.mDay: LUGGING REPORT 1st plug sanded b Dugh bailer, pumped 300 lbs. hulls, 10 sx gel Ex cement down 8 5/8".	x cement, 10 sx ge1, 1 sx hul posal Received by Richar All X Part 14 Month: 5 ack to 4250' and dumped 5 sx , 50 sx cement, 10 sx ge1, 10 psi.	d Lacey [ECHNICIAN] None Year: 19 91 cement on top of 0 lbs. hulls,

DATE <u>5-22-9/</u>

MAY 17 1991

en Gordina (TECHNICIAN)