

STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
 File One Copy

Lease Owner Graham-Michaelis Drlg. Co. Address 211 North Broadway, Wichita Ks.
 (Applicant)

Lease (Farm Name) WILLIAMSON Well No. 1

Well Location SE NW SE Sec. 11 Twp. 30S Rge. 19 (~~XX~~) (W)

County Kiowa Field Name (if any) _____

Total Depth 5130' Oil Gas Dry Hole x

Was well log filed with application? Yes If not, explain: _____

Date and hour plugging is desired to begin as soon as possible

Plugging of the well will be done in accordance with the Rules and Regulation of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Wayne Clark Address 2011 Fuller St., Winfield, Ks.

Plugging Contractor Graham-Michaelis Drilling Company

Plugging Contractor's License No. _____

Address 211 North Broadway, Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Graham-Michaelis Drlg. Co. Address 211 North Broadway, Wichita, Ks.

and payment will be guaranteed by applicant.

RECEIVED
 STATE CORPORATION COMMISSION

JUN 18 1957

CONSERVATION DIVISION
 Wichita, Kansas

6-18-1957

W. A. Michaelis
 Applicant or Acting Agent

Date June 14, 1957

PLUGGING
 FILE SEC. 11 T. 30 R. 19W
 BOOK PAGE 19 LINE 13



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS
 June 11, 1957

Well No. 1
 Lease Williamson
 Description SE NE SE 11-30-19W
 County Kiowa
 File No. 19-13

Graham-Michaelis Drilling Co.
 211 North Broadway
 Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Ruel Durkee, Box 597, McPherson, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

BY S. S. Greider
 S. S. Greider
 WELL PLUGGING SUPERVISOR.

cc:
 District Plugging Supervisor