

15-159-05234-0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
500 INSURANCE BUILDING
212 NORTH MARKET
WICHITA, KANSAS 67202

FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Pat Simmons
Address 5252 No. Broadway - Wichita, Kansas
Lease (Farm Name) Raney Well No. 2
Well Location S1/4 NE 1/4 SE Sec. 3 Twp. 21 Rge. 6 W (E) (W)
County Lin Field Name (If Any)
Total Depth 3381' Oil Well Gas Well Input Well SWD Well D & A
Well Log filed with application yes or Well Log filed with Plugging Supervisor

Date and hour plugging is desired to begin July 25, 1969
Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of company representative in charge of plugging operations Cliff Cradell
Address Weldon, Kansas

Plugging Contractor Art Lamb Consulting License No. 440
Address 2809 King St - Hutchinson, Kansas

Invoice covering assessment for plugging this well should be sent to Pat Simmons
5252 No. Broadway Address Wichita, Kansas
and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION
JUL 24 1969
CONSERVATION DIVISION
Wichita, Kansas

Signed: Art Lamb
Applicant or Acting Agent
Date: 7-23-69

State of Kansas



15.159.05234.0000

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

500 Insurance Bldg. 212 N. Market
WICHITA, KANSAS 67202

July 24, 1969

RECEIVED
STATE CORPORATION COMMISSION

AUG 14 1969

CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING AUTHORITY

Well No.	2
Lease	Rainey
Description	SW NE SE 3-21-6W
County	Rice
Total Depth	3381'
Plugging Contractor	Art Lamb Casing Pulling


Pat Simmons
5252 N. Broadway
Wichita, Kansas 67219

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Very truly yours,


J. Lewis Brock, Administrator

~~Mr. Hugh Scott, P. O. Box 924, McPherson, Ks., 67460~~
is hereby assigned to supervise the plugging of the above named well.