Form CP-4

STATE OF KANSAS
STATE CORPORATION COMMISSION
Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission

WELL PLUGGING RECORD

State Corporation Commission 212 No. Market			Сошту	· 260	Twp. 2I Rge	C. TITL 12	
Wichita, Kansas 67202 NORTH	Location as "NE		or footage from	n lines 1	iv ne sw		
NORTH	Lease Owner						
i f i	Lease Name	Rei	inov			Well No	6
	Office Address_	529	52 North	Broadway	. Wichita	. Kansa	<u> </u>
 	Character of We						
i l i	Date well comp						1947
1 1	Application for I						
	Application for p						1970
i i	Plugging comme						1970
1 1	Plugging comple					7-22	1970
	Reason for abanc						
ili	<u> </u>						
	If a producing v	well is abandon	ed, date of las	t production.	<u> </u>		19
	Was permission			_			
Locate well correctly on above Section Plat	menced?	Y	ad				·
ne of Conservation Agent who s	supervised plugging of this	well	Gilbert	Toman			
ducing formation			Bottom		Total Depth o	of Well <u>34</u>	I9 Feet
w depth and thickness of all wa	ater, oil and gas formations	s.					
OIL, CAS OR WATER RECO	ORDS					CASING F	RECORD
			1	<u> </u>	7		
FORMATION	CONTENT	FROM	YO .	SIZE	PUT IN	-	ED DUT
	TATE CORPORATION			7"	-	2,	504'
			 				· · ·
	JUL 24 19	MOISSIMI	 				
	CONSES. 4 19	7 0	+	-	 		
	TO TOUR TOWN		 			 	
	Wichita, Kans	is CON	 -				
			 		+		
Describe in detail the manne ntroducing it into the hole. If		Plugged 3419 to 215'	off bott 3375	same and der on of hol Dumped 6	_	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
introducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 215'	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
introducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
introducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
introducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
introducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
introducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. If	cement or other plugs wer	Plugged 3419 to 2151 of Ready	off bott off bott o 3375! Made 15	same and der on of hol Dumped 6	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. If	cement or other plugs wer	Pluggad 3419' to to 215'. af Raady collar.	off bott off bott off bott off bott off bott Made I50 wix Come	same and der	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. Iffeet for each plu	cement or other plugs wer ag set. (If additional	Plugged 3419 to 2151 of Ready	off bott off bott off bott off bott off bott Made I50 wix Come	same and der	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. Iffeet for each plufeet for each plu	cement or other plugs wer ag set. (If additional	Pluggad 3419' to to 215'. af Raady collar.	off bott off bott off bott off bott off bott Made I50 wix Come	same and der	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. Iffeet for each plufeet for each plu	cement or other plugs wer ag set. (If additional	Pluggad 3419' to to 215'. af Raady collar.	off bott off bott off bott off bott off bott Made I50 wix Come	same and der	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. Iffeet for each plune of Plugging Contractor	cement or other plugs wer	Pluggad 3419' to to 215'. af Raady callar.	off bott off	same and der	oth placed, from le with sa sx of cen bridge.	ind. San ient. Mu Dumped	feet to d from dded hel 6 Yrds.
ntroducing it into the hole. Iffeet for each plu	cement or other plugs wer	Pluggad 34191 to to 2151. af Read; callar.	off bott 3375 Made I5 Wix Come	same and der	th placed, from le with sa sx of com bridge, ing to the	and. Santent. Mu Dumped bottom	feet to
ntroducing it into the hole. Iffeet for each plu	(If additional of	Pluggad 34191 to to 2151. af Read; collar.	off bott 3375! Made I5 Wix Come ssary, use BACK employee of o	same and der on of hold Dumped 6 of rech of this sheet) where or (ow	oth placed, from Le with sa sx of com bridge, ing te the	and. Santent. Mu Dumped bottom	ye-described
ntroducing it into the hole. Iffeet for each plu	(If additional of the country of the	Pluggad 3419' to 215'. of Ready collar.	off bott 3375! Made I5 Wix Come seary, use BACK employee of offacts, stateme	same and der on of hold Dumped 6 of rech of this sheet) where or (ow	oth placed, from Le with sa sx of com bridge, ing te the	and. Santent. Mu Dumped bottom	ye-described
ntroducing it into the hole. Iffeet for each plune of Plugging Contractor dress	(If additional of the country of the	Pluggad 3419' to 215'. of Ready collar.	off bott 3375! Made I5 Wix Come seary, use BACK employee of offacts, stateme	same and der on of hold Dumped 6 of rech of this sheet) where or (ow	oth placed, from Le with sa sx of com bridge, ing te the	and. Santent. Mu Dumped bottom	ye-described
introducing it into the hole. If	(If additional of that I have knothat the same are true and	Pluggad 3419' to 215'. of Ready collar.	off bott 3375! Made I5 Wix Come seary, use BACK employee of offacts, stateme	same and der on of hold Dumped 6 of rech of this sheet) where or (ow	oth placed, from Le with sa sx of com bridge, ing te the	and. Santent. Mu Dumped bottom	ye-described
ntroducing it into the hole. Iffeet for each plune of Plugging Contractor dress	(If additional of that I have knothat the same are true and	Pluggad 3419' to 215'. of Ready collar. MTY OF	off bott 3375! Made I5 Wix Come seary, use BACK employee of offacts, stateme	same and der on of hold Dumped 6 of rech of this sheet) where or (ow	oth placed, from Le with sa sx of com bridge, ing te the	and. Santent. Mu Dumped bottom	ye-described
ntroducing it into the hole. Iffeet for each plune of Plugging Contractor dress	(If additional of that I have knothat the same are true and	Pluggad 3419' to 215'. of Ready collar. MTY OF	off bott 3375! Made I5 Wix Come seary, use BACK employee of offacts, stateme	same and der on of hold Dumped 6 of rech of this sheet) where or (ow	oth placed, from Le with sa sx of com bridge, ing te the	and. Santent. Mu Dumped bottom	ye-described
ntroducing it into the hole. Iffeet for each plune of Plugging Contractor dress	(If additional of the same are true and	Pluggad 3419' to to 215'. af Raady callar. MTY OF	off bott 3375! Made I55 Mix Cone employee of offacts, statementely made God.	same and der on of hold Dumped 6 of rech of this sheet) where or (ow	oth placed, from le with sa sx of com bridge, ing to the	and. Santent. Mu Dumped bottom	ye-described
ntroducing it into the hole. Iffeet for each plu	(If additional of the same are true and	Pluggad 3419' to 215'. of Ready collar. MTY OF	off bott 3375! Made I55 Mix Cone employee of offacts, statementely made God.	same and der on of hold Dumped 6 of rech of this sheet) where or (ow	oth placed, from le with sa sx of com bridge, ing to the	and. Santent. Mu Dumped bottom	ye-described
ntroducing it into the hole. Iffeet for each plu	(If additional of the same are true and	Pluggad 3419' to to 215'. af Raady callar. MTY OF	off bott 3375! Made I55 Mix Cone employee of offacts, statementely made God.	same and der on of hold Dumped 6 of rech of this sheet) where or (ow	oth placed, from le with sa sx of com bridge, ing to the	of the abouted and the	ye-described

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY

15.159.04110.0000

412 Union National Bk. DMg., Wichita, Kansas

Company - H. C. BENNETT Farm - Roinoy

No. 6

ह्य 6न 3 ĩ. 21 SEC. NA NE SU

Total Depth. 34191 Comm. 9-6-47

Comp. 9-25-47

Shot or Treated.

Contractor.

tssued. 11-22-17

Rt.30 County.

KANSAS

10-3/4"

CASING: 143 Com. w/140 ax

711 3491' Com. w/ 75 sx El .votion.

Production. Est. 50 bbls oil

Figures indicate Bottom of Formations.

sand, rod bod & shale 145 shalo & shalls 750 875 salt & shale limo & shalo 965 shalo & sholla 1035. limo 🤄 shalo . 1150 limo 1160 shalo & lime 2170 shalo à sholls 2220 limo 🌣 shalo 2290 limo, sholls & shale 2385 lime sticky & shale 2430 limo 2610 lime a shalo 2640 shale sdy, sand & limo 2740 2750 limo ⇔ shalo limo 2798 limo & shalo 2805 limo 2830 limo & shalo 2940 šhalo & sholls 2969 limo & shalo 2989 limo 3305 limo & shalo 3396 3400 conglomorato ohat 3419

STATE CORPORATION COMMISSION CONSERVATION OIVISION JUL 17 1970

Tops:

Total Dopth

Conglomerato 3386 3403 Mississippian