

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

15.185.11703.0000

WELL PLUGGING APPLICATION FORM

Lease Owner Petroleum, Inc. Address 100 Derby Bldg., Wichita, Kansas
(Applicant)

Lease (Farm Name) Pundsack Well No. 2

Well Location NE SW NW Sec. 1 Twp. 2 Rge. 13 (R)-(W)

County Stafford Field Name (if any) Pundsack, N

Total Depth 3711 Oil Gas Dry Hole x

Was well log filed with application? . If not, explain:

Herewith

Date and hour plugging is desired to begin January 10, 1952

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.
(Use an additional sheet if necessary)

Name of the person on the lease in charge of well for owner

Mr. Claude W. Bard Address 1201 Taft, Great Bend, Ks.

Name of Plugging Contractor Garvey Drilling Company

Address Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to

Petroleum, Inc. Address 100 Derby Bldg., Wichita, Kansas

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

1-22-52 JAN 22 1952

CONSERVATION DIVISION
Wichita, Kansas
PLUGGING
FILE NO. 19-127-R-132
BOOK PAGE 137 LINE 25

Eric H. [Signature]
Applicant or Acting Agent

Date January 10, 1952



15.185.11703.0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

January 14, 1952

Well No.	2
Lease	Pundsack
Description	NE SW NW 19-21-13W
County	Stafford
File No.	137-25

Petroleum, Inc.
100 Derby Bldg.
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. C. D. Stough, Box 207, Great Bend, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: J. P. Roberts
J. P. ROBERTS

cc: DISTRICT PLUGGING SUPERVISOR