

KANSAS

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION AGENT'S REPORT

RECEIVED  
STATE CORPORATION COMMISSION  
MAR 2 1972  
CONSERVATION DIVISION  
Wichita, Kansas

J. Lewis Brock  
Administrator  
500 Insurance Building  
Wichita, Kansas 67202

Operator's Full Name Petroleum Inc.  
Complete Address 8th floor R.H. Garvey Bldg. 300 W. Douglas Wichita, Ks  
Lease Name Schartz Well No. 1  
Location SW Sec. 20 Twp. 21 Rge. 13 (E) W  
County Stafford Total Depth 840  
Abandoned Oil Well        Gas Well        Input Well        SWD Well        D & A         
Other well as hereafter indicated 4 3/4" shot hole  
Plugging Contractor Central Exploration Co. Inc.  
Address 930 Sutton Place Wichita, Ks License No.         
Operation Completed: Hour 12:30 PM Day 29 Month 2 Year 1972

The above well was plugged as follows:

Drill shot hole-4 3/4" to 840 ft. Shove plug to 500 ft. Cement  
through drill pipe with 35 sacks. Bridge at 40 ft, 4 sacks cement  
to surface.

I hereby certify that the above well was plugged as herein stated.

INVOICED

Signed: M. Russell Bickerton  
Well Plugging Supervisor

DATE 3-3-72

INV. NO. 5280-02



15.185.19496.0000

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

500 Insurance Bldg. 212 N. Market  
WICHITA, KANSAS 67202

VERBAL PERMIT FORM  
(To Be Filed By Plugging Agent)

RECEIVED  
STATE CORPORATION COMMISSION  
MAR 2 1972  
CONSERVATION DIVISION  
Wichita, Kansas

J. Lewis Brock  
Administrator  
500 Insurance Building  
Wichita, Kansas 67202

Dear Sir:

Mr. Pettit of Central Exploration Co has this date requested permission to plug the following described well:

Mr. Pettit guarantees payment of the plugging fee.

Operator's full Name: Petroleum Inc.

Wichita, KS

Complete Address: 8th floor R.H. Garvey Bldg. 300 W. Douglas

Lease Name: Schartz Well No. 1

Location: SW Sec. 20 Twp. 21 Rge. 13 (E)(W) W

County: Stafford Total Depth 840 Oil Well     

Gas Well      Input Well      SWD Well      D & A      ~~Lost Hole~~ shot hole

Mr. Pettit was instructed to plug the well as follows:

Drill shot hole-4 3/4" to 840 ft. Shove plug to 500 ft.

Cement through drill pipe with 35 sacks. Bridge at 40 ft,

4 sacks cement to surface.

Very truly yours,

*Russell B. Johnston*  
Conservation Division Agent