Form CP-4

Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Consert John Division State-Corporation Commission 211 No. Broadway Wichita, Kansas

WELL PLUGGING RECORD

211 No. Broadway Wichita, Kansas	Stai	ford					
NORTH	Location as "N	E/CNW#SW#" (or footage fr			/4	
<u> </u>		Clay New					
		Pile				Well l	No. <u>3</u>
1 1		Stafford,	, — —				
		Vell (completed :					
		pleted plugging filed			1		19
	Application for	plugging filed_			Februar		19 62 19 62
	Application for	plugging filed_ plugging approv enced	/ea		Februar		19 62
i } i	Plugging compl	leted			Februar		
· — - ¦		ndonment of well					
iii		<u> </u>	<u>.·</u>		economica	1 to op	erate
! ! !		well is abandone					
Locate well correctly on shove		a obtained from	the Conser	vation Division		efore plugg	ging was com-
Locate well correctly on above Section Plat	menced?						
ne of Conservation Agent who su ducing formation						Lakamp	
w depth and thickness of all wat	er oil and gas formation	pepta to top	Botto	m	_ Total Depth	of Well_3	Feet
		15. 6					
OIL, GAS OR WATER RECO	RDS					CASING	RECORD
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	Pu	LLEB OUT
				8-5/8 ^V	403'	Non	.e
		a • :					
		 					
		ļ		 			
		 		 			
		 	 		 		
							
ntroducing it into the hole. If confect for each plug	ement or other plugs we set. Hole	exe used, state the	ae character	of same and de	cks of	method or	methods used
ntroducing it into the hole. If co	ement or other plugs we set. Hole cemen 2210	sanded to nt dumped v feet of 5-	3500 fe	et. 5 sactor. Pull h casing.	cks of Led Mudded ho	n	methods used
ntroducing it into the hole. If co	ement or other plugs we set. Hole cement 2210 to 40 390	sanded to nt dumped v feet of 5- 00 feet. S feet. Dumy	3500 fe	et. 5 sad lor. Pull h casing. bridge flacks of ce	cks of led Mudded he rom 400 to	n	methods used
ntroducing it into the hole. If co	Hole cemer 2210 to 40 390 bride	sanded to nt dumped v feet of 5- 00 feet. S feet. Dump	3500 fevith bai	et. 5 sactor. Pull h casing. bridge fracks of ceto 40 feet	eks of led Mudded he rom 400 to ement on	n	methods used
atroducing it into the hole. If co	Hole cement 2210 to 40 390 bridg	sanded to nt dumped v feet of 5- 00 feet. S feet. Dumy	3500 fevith bai	et. 5 sactor. Pull h casing. bridge fracks of ceto 40 feet	eks of led Mudded he rom 400 to ement on	n	methods used
ntroducing it into the hole. If co	Hole cement 2210 to 40 390 bridg	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde	3500 fevith bai	et. 5 sactor. Pull h casing. bridge fracks of ceto 40 feet	eks of led Mudded he rom 400 to ement on	n	methods used feet to
introducing it into the hole. If co	Hole cement 2210 to 40 390 bridg	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde	3500 fevith bai	et. 5 sactor. Pull h casing. bridge fracks of ceto 40 feet	eks of led Mudded he rom 400 to ement on	n	Methods used feet to
introducing it into the hole. If co	Hole cement 2210 to 40 390 bridg	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde	3500 fevith bai	et. 5 sactor. Pull h casing. bridge fracks of ceto 40 feet	eks of led Mudded he rom 400 to ement on t. Rock th cement	n	Methods used feet to f
ntroducing it into the hole. If co	Hole cemer 2210 to 40 bridge to be	sanded to nt dumped v feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell	3500 fevith bai-1/2 inc Set_rock ped_20 sed_hole set_fill	et. 5 sactor. Pull h casing. bridge fracks of cete to 40 feet ed hole wi	cks of Led Mudded herom 400 to ement on t. Rock th cement	ole FORATION UN 26	Feet to
ntroducing it into the hole. If confect for each plug	Hole cement 2210 to 40 390 bridg	sanded to nt dumped v feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell	3500 fevith bai-1/2 inc Set_rock ped_20 sed_hole set_fill	et. 5 sactor. Pull h casing. bridge fracks of cete to 40 feet ed hole wi	cks of Led Mudded herom 400 to ement on t. Rock th cement	ole FORATION UN 26	Feet to
ntroducing it into the hole. If confect for each plug	Hole cemer 2210 to 40 bridge to be	sanded to nt dumped v feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell description fulfit	3500 fevith bai	et. 5 sactor. Pull h casing. bridge fracks of cete to 40 feet ed hole wi	cks of Led Mudded herom 400 to ement on t. Rock th cement	ole FORATION UN 26	Feet to
ntroducing it into the hole. If confect for each plug	Hole cemer 2210 to 40 390 bridg bridg to be	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell description Full Is nwood, Kans	3500 fevith bai 1/2 inc Set_rock ped_20 s ed_hole set_fill lar.	et. 5 sactor. Pull h casing. bridge fracks of ceto 40 feeted hole with the state of	cks of Led Mudded herom 400 to ement on t. Rock th cement	ole FORATION UN 26	Feet to
ntroducing it into the hole. If confect for each plug ne of Plugging Contractor	Hole cemer 2210 to 40 390 bridg bridg to be	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell description fulfits nwood, Kans	3500 fevith bai 1/2 inc Set_rock ped_20 s ed_hole set_fill lar.	et. 5 sactor. Pull h casing. bridge fracks of ceto 40 feeted hole with the state of	cks of Led Mudded herom 400 to ement on t. Rock th cement	ole FORATION UN 26	Feet to
ntroducing it into the hole. If confect for each plug me of Plugging Contractor lress TE OF Kansas John Being first duly sworn on oath	Glenn & Smith Box 114, Elli; COU	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell description puffs nwood, Kans	3500 fevith bai 1/2 inc. Set_rock ped_20 sed_hole. Set_fill lar.	et. 5 sactor. Pulling fracks of certo 40 feeted hole with the short of contract of the short of	cks of led Mudded herom 400 to ement on t. Rock th cement	ole FORATION UN 2 6 EVATION ichita, K	COMMISSION 1904 1 DIVISIUM ansas
Introducing it into the hole. If confect for each plug me of Plugging Contractor dress	Glenn additional Glenn Smith Box 114, Ellis COU , says: That I have known at the same are true an	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell description fulfill nwood, Kans NTY OF	3500 fevith bai 1/2 inc. Set_rock ped_20 sed_hole. Set_fill lar.	et. 5 sactor. Pulling fracks of certo 40 feeted hole with the short of contract of the short of	cks of led Mudded herom 400 to ement on t. Rock th cement	ole FORATION UN 2 6 EVATION ichita, K	COMMISSION 1904 1 DIVISIUM ansas
ntroducing it into the hole. If confect for each plug me of Plugging Contractor lress ATE OF Kansas I, being first duly sworn on oath	Glenn additional Glenn Smith Box 114, Ellis COU , says: That I have known at the same are true an	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell description puffs nwood, Kans	3500 fevith bai 1/2 inc. Set_rock ped_20 sed_hole. Set_fill lar.	et. 5 sactor. Pulling fracks of certo 40 feeted hole with the short of contract of the short of	cks of led Mudded herom 400 to ement on t. Rock th cement	ole FORATION UN 2 6 EVATION ichita, K	COMMISSION 1904 1 DIVISIUM ansas
ntroducing it into the hole. If confect for each plug the of Plugging Contractor tress TE OF Kansas being first duly sworn on oath ye-described well as filed and th	Glenn & Smith Box 114, Ellir COU , says: That I have knoat the same are true an	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell nwood, Kans NTY OF	3500 fevith bai 1/2 inc. Set_rock ped_20 sed_hole. Set_fill lar.	et. 5 sactor. Pulling fracks of certo 40 feeted hole with the short of contract of the short of	cks of led Mudded herom 400 to ement on t. Rock th cement	ole FORATION UN 2 6 EVATION ichita, K	COMMISSION 1904 1 DIVISIUM ansas
ntroducing it into the hole. If confect for each plug me of Plugging Contractor ress TE OF	Glenn & Smith Box 114, Ellir COU , says: That I have knoat the same are true an	sanded to nt dumped w feet of 5- 00 feet. S feet. Dump ge. Mudde ge to 30 fe ase of cell description fulfill nwood, Kans NTY OF	3500 fevith bai 1/2 inc. Set_rock ped_20 sed_hole. Set_fill lar.	et. 5 sactor. Pulling fracks of certo 40 feeted hole with the short of contract of the short of	cks of led Mudded herom 400 to ement on the Rock th cement CONSE We of the content of the content on the content of the conte	ole FORATION UN 2 6 EVATION ichita, K	COMMISSION 1904 1 DIVISIUM ansas

CLAY NEWELL

INVOICE

15.185.10809:0000

Ralph Glenn Phone 449-R

Glenn & Smith Pipe Pulling Co.

R. E. Smith Phone 582-R

Box 114

ELLINWOOD, KANSAS

Date 2/1/62

Invoice No. ____3_

Well No. _____3__

Sec. 27 - 21 - 14

Lease Pile

* * * * * * * * * * * * * * * * * * * *				
1/30/62	Cleaning at 3540 3540 to	and ru	a 5 sac	No. No. No.
1/31/62	Working :	24" ten		op.

` ,	,	.'	29971 21951	2900	27	75	
1		٠,	2195	, and	SUBLE	ac 5	
2/1	/62	•	Mudded	מוטיד'ד	35001	to A	

2/1/62	Mudded from 3500) to	ek bridge	4001
•	to 385° and run	3 sag	ement from	n 385 °
	to 3761 •			

2/ 2/62	
	from 376 to 325 mudded from 325 to 40
	rock and 10 sacks of cement from 40 to base
	of celler.

3 hrs.	

4 hrs.	•	28.00
, , , , ,		-
	· .	7.10

20 hrs @ {	7.00	per	hr.
7 shots @	\$ 10.	00 pc	er hr
22121 52"	@ .20	per	foot

٠	442,40
<u> </u>	
	7 700 100

21.00

652,40

PERMIT NO. 396 STATE PLUGGER: W. L. Lockamp RECEIVED COMMISSION

APR 6 1962

ONSERVATION DIVISIO