Rev. 6-3-74 FORM CP-1

STATE OF KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION P. O. BOX 17027 WICHITA, KANSAS 67217

RECEIVED STATE CORPORATION COMMISSION

WELL PLUGGING APPLICATION FORM File One Copy

NOV 0 1 1977

CONSERVATION DIVISION Wichita, Kansas

API Number 15-165-20640.00.00 this well)
Lease Owner J. C. Musgrove, Inc.
Address Box 611, Great Bend, Kansas 67530
Lease (Farm Name) Schroeder Well No. #1
Well Location 100: N-SE/SW/NE Sec. 26 Twp. 18 Rge. 16 (E) (W) X
County Rush Total Depth 3580: Field Name
Oil Well X Gas Well Input Well SWD Well Rotary D & A
Well Log attached with this application as required yes
Date and hour plugging is desired to begin as soon as possible
PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION. Name of company representative authorized to be in charge of plugging operations:
J.C. Musgrove Address Box 611 Great Bend, Kansas 67530
Plugging Contractor Rockhold Engineering, Inc. License No. 670
Address Box 698, Great Bend, Kansas 67530
Invoice covering assessment for plugging this well should be sent to:
Name J. C. Musgrove, Inc.
Address Box 611, Great Bend, Kansas 67530
and payment will be guaranteed by applicant or acting agent.
Signed: Ames W. Rockhold James W. Rockhold

Date: October 31, 1977

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)
245 North Water
WICHITA, KANSAS 67202

November 1, 1977

WELL PLUGGING AUTHORITY

Well No.

Lease

Description

County

Total Depth

Plugging Contractor

1

Schroeder

100' N SE SW NE Sec. 26-18-

Rush 3580 164

Rockhold Engineering, Inc.

J. C. Musgrove, Inc. Box 611 Great Bend, Kansas 67530

Gentlemen:

named well.

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

Mr. Leo Massey, 109 West 15th, Hays, Kansas 67601
is hereby assigned to supervise the plugging of the above