15.135.23914.0000

KCC OIL/GAS REGULATORY OFFICE

DATE	[] New Situation	
OPERATOR Prospect Oil & Gas, Inc. # 6627	[] Response to Reques [] Follow-up E/2 W/2	
P.O. Box 837 NAME Russell, KS 67665	LOCATION SE SE ,SEC 8,T 20 S,R 24	M X ^E X
& ADDRESS	LEASE South Hair Well # 1-8	
PHONE NO. OPER. 913-483-6266 OTHER REASON FOR INVESTIGATION: Alternate II cementi PROBLEM: PERSON(S) CONTACTED: Brad Hutchinson w/Prosp	DEC 71995	LEASE INSPECTION
FINDINGS: Opened DV tool on 12/4/95 and pum had only a very slight blow. Witnessed by Ste 12/5/95 4:40 p.m. ECI ran a temperature surv squeeze from surface.	mped 400 sx cement. Well did not circulate a eve Middleton. vey. TOC @ 375'. District approved bullhead	COMPLAINT pu
12/6/95 Squeezed backside with 75 sx cement. pressure 150 psi. Job completed at 9:45 a.m.	Maximum pressure 400 psi and shut in	
ACTION/RECOMMENDATIONS:	photos taken:	FIELD REPORT
Retain 1 copy Joint District Office Send 1 copy Conservation Division	BySteve Durrant	_ > >