

AX Status Review - Field Report

RBDMS Well Information

Well Name:

API:

County:

District:

Quarter Calls	Section	Township	Range	RangeDir
SWSENE	3	24	18	E
Latitude:	37.98888	Footage	N/S	Footage
Longitude:	-95.412819	3135	S	1155
				E/W
				E

Agent Findings

Agent:

Inspection Date:

Per my determination, this Well Status in RBDMS should be coded:

Well Status:	INactive	PRoducing	Active Inj/Disp	Plug/Abandoned	ReCompleted	EXpired Permit
<small>(Check One)</small>						X

Comments: I arrived on the Cimarron Lease around 7:30 am on 8/9/2017. I went to the location where well #5 was suppose to be located. No well was found above ground. I used a metal detector around the location and no metal was located. Only information I could find was an expired intent. I attached the expired intent with this field report. While I was on site, I did locate twelve (12) abandoned wells on this property. I will provide another field report with all the information for those wells.

Photo Taken?

Central Office Staff has reviewed the available electronic databases (RBDMS, KGS, Walters, etc) and in-house files. Central Office Staff has been unable to determine the proper Well Status code of this record. District Field Agents are responsible for District file research and the on-location field inspection to update this well record. Please submit any additional documentation supporting the updated status as they may be imaged and intregated into RBDMS.

Information Update

*Latitude:		Footage	N/S	Footage	E/W
*Longitude:					

Potential Responsible Party:	License #:

***Field agent is responsible for updating the LOCATION PER KCC (GPS) fields in RBDMS.**

Questions: Debbie Rush (316) 337-6204, d.crawford-rush@kcc.ks.gov
 Patrick Shields (316) 33-6035, p.shields@kcc.ks.gov