

RECEIVED
STATE CORPORATION SOMMISSION

CONSERVATION DIVISION AGENT'S REPORT

JUN 2 8 1961

Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas

CONSERVATION DIVISION Wichita, Kansas

| File No. | | _County: | Barto | n , | | | |
|--|--|---------------------------------------|-------------|-----------------|-------------------|---------------|---------------|
| Location: · SW | SW NE | Sec | 29 | _Twp2 | O_Rge. | <u>15W</u> (E | (W) |
| Name of Field: | <u> </u> | · · · · · · · · · · · · · · · · · · · | | _Total D | epth: | 3850 ' | |
| I have this date comp | leted super | vision of plu | igging of | : | | | |
| Lease Name: | Ross | · · · · · · · · · · · · · · · · · · · | | · | _Well No. | # 1 | <u> </u> |
| Operator's Full Name: | Messmon& | Rinehart | Oil Co. | <u> </u> | | | |
| Complete Address: | 518 Petr | oleum Bldg | ., Wich | ita, <u>K</u> a | nsas | · , | |
| Plugging Contractor:_ | Southwes | t Casing P | ulling | Co., In | c : | | |
| Address: | Box 364, | Grea t Be | nd, Kan | sas | _License | No. 399 | 9 |
| Oil Well Gas | We11X | Input We | .1 | swd w | ell | D & A_ | |
| Other well as hereaft | er indicated | d: | | | · | | : |
| Was any delay in plug | ging operat: | ions caused l | y Conser | vation D | ivision A | gent? Yes | No X |
| If yes how long? | - ; | ; | Reason: | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | - | _ | | |
| Operation Completed: | Hour | Day_ | 24 | Mont | h6 | | Year 1961 |
| Operation Completed: The above well was pl | • ' | • | 24 | Mont | h6 | | Year 1961 |
| ••• | ugged as fol | llows: | | - | | | |
| The above well was pl | ugged as for | llows: 5 sax ceme | nt with | dump b | ailer. | Pulled pi | pe • |
| The above well was pl | ugged as for 0 3750; & th 30 sax | llows: 5 sax ceme mud & 100 | nt with | dump b | ailer. h Globe | Pulled pi | pe • |
| The above well was pl Sand back to Squeezed well wit | ugged as for 0 3750; & th 30 sax | llows: 5 sax ceme mud & 100 | nt with | dump b | ailer. h Globe | Pulled pi | pe • |
| The above well was pl Sand back to Squeezed well wit | ugged as for 0 3750; & th 30 sax | llows: 5 sax ceme mud & 100 | nt with | dump b | ailer. h Globe | Pulled pi | pe • |
| The above well was pl Sand back to Squeezed well wit | ugged as for 0 3750; & th 30 sax | llows: 5 sax ceme mud & 100 | nt with | dump b | ailer. h Globe | Pulled pi | pe • |
| The above well was pl Sand back to Squeezed well wit | ugged as for 0 3750; & th 30 sax | llows: 5 sax ceme mud & 100 | nt with | dump b | ailer. h Globe | Pulled pi | pe • |
| The above well was pl Sand back to Squeezed well wit | ugged as for 0 3750; & th 30 sax | llows: 5 sax ceme mud & 100 | nt with | dump b | ailer. h Globe | Pulled pi | pe • |
| The above well was pl Sand back to Squeezed well wit | ugged as for 0 3750; & th 30 sax | llows: 5 sax ceme mud & 100 300' to b | nt with | dump bent wit | ailer. | Pulled pi | pe. |

Remarks:

INVOIÇED

DATE 6/29/61 INV. NO. 3336-W