Mive All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
212 No. Market

WELL PLUGGING RECORD

212 No. Market Wichita, Kansas	· · · · · · · · · · · · · · · · · · ·				··P·8·	21 (E) W (W)	
NORTH	Location as "N	IE/CNW#SW#"	or footage fro	m lines NW	SW		
	Lease Owner_			Company			
		Lease Name <u>Elmore G#1</u> Well No Office Address Great Bend, Kansas 67530					
1 1	1	Character of Well (completed as Oil, Gas or Dry Hole) Date well completed 19					
i l	1	r plugging filed			<u> </u>		
		plugging approv					
j j j	Plugging comm	nenced 9	18/67			19	
1	Plugging comp	oleted 9/	20/67			19	
	Reason for aba	andonment of well	or producing	g formationde	pleted.		
i							
	If a producing	well is abandone	ed, date of la	st production		19	
Locate well correctly on above			the Conserv	ation Division or	its agents befor	re plugging was com	
Section Plat	menced?				 '		
ame of Conservation Agent who sup						Well 4160 Fee	
roducing formation			Botton	· · · · · · · · · · · · · · · · · · ·	Total Depth of V	Well 4100 Fee	
how depth and thickness of all water	er, oil and gas formation	ons.	•				
OIL, CAS OR WATER RECOR	RDS				C	ASING RECORD	
	DONTENT	FROM	70				
FORMATION	CONTENT	FROM	מד	SIZE O E / OST	PUT IN	PULLED OUT	
			-	8-5/853	40 7 8	none	
		1		5-1/2**	4159*	3297*	
feet for each plug Checked hole cement. Cut	to 4160°, ran	sand to 407	e character of	w same and depth lumped 5 sac d, shot pi	n placed, from cks of pe at		
Checked hole cement. Cut 3277 and it welded on sur	ement or other plugs w set. to 4160°, ran	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud,		
Checked hole cement. Cut 3277 and it welded on sur	to 4160°, ran off poor boy h came loose. P	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud,		
Checked hole cement. Cut 3277 and it welded on sur 100 sacks of	to 4160°, ran off poor boy h came loose. P	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud,		
Checked hole Checked hole cement. Cut 3277 and it welded on sur 100 sacks of	to 4160°, ran off poor boy h came loose. P	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud,		
Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement.	to 4160°, ran off poor boy h came loose. Pr face, Sun Cemer cement and 7 s	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud,		
Checked hole Checked hole cement. Cut 3277 and it welded on sur 100 sacks of	to 4160°, ran off poor boy h came loose. Pr face, Sun Cemer cement and 7 s	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud,		
Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement.	to 4160°, ran off poor boy h came loose. Pr face, Sun Cemer cement and 7 s	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud,		
Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement.	to 4160°, ran off poor boy h came loose. Pr face, Sun Cemer cement and 7 s	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud,		
Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement.	to 4160°, ran off poor boy h came loose. Pr face, Sun Cemer cement and 7 s	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud, h 20 sacks	feet t	
Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement.	to 4160°, ran off poor boy h came loose. Pr face, Sun Cemer cement and 7 s	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	umped 5 sadd, shot pi	cks of pe at collar of mud, h 20 sacks	feet t	
Checked hole cement. Cut 3277' and it welded on sur 100 sacks of of cement.	to 4160°, ran off poor boy h came loose. Pr face, Sun Cemer cement and 7 s	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	dumped 5 sadd, shot pi	cks of pe at collar of mud, h 20 sacks	feet t	
Checked hole cement. Cut 3277' and it welded on sur 100 sacks of of cement.	to 4160°, ran off poor boy h came loose. Pr face, Sun Cemer cement and 7 s	sand to 407 ead, had houlded 103 justing Compa	e character of the loade oints of the pumper.	d same and depth lumped 5 same and same and lumped 5 same and lumped 6 same and lump	cks of pe at collar of mud, h 20 sacks	feet t	
Checked hole cement. Cut 3277' and it welded on sur 100 sacks of of cement.	to 4160°, ran off poor boy h came loose. Pr face, Sun Cemer cement and 7 s	sand to 407 ead, had ho ulled 103 j nting Compa acks of muc	e character of the character of the loade oints of the character of the ch	dumped 5 saded, shot pi	cks of pe at collar of mud, h 20 sacks	feet t	
Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement. PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Ceme cement and 7 s	sand to 407 ead, had ho ulled 103 nting Compa acks of muc	e character of the loade oints o	dumped 5 saded, shot pi	cks of pe at collar of mud, h 20 sacks	feet t	
Checked hole Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement. PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Ceme cement and 7 s (If additiona KNIGHT CASING	sand to 407 ead, had he ulled 103 nting Compa acks of muc	e character of the loade oints o	dumped 5 saded, shot pi	cks of pe at collar of mud, h 20 sacks	feet t	
Checked hole Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement. PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Ceme cement and 7 s	sand to 407 ead, had he ulled 103 nting Compa acks of muc	e character of the loade oints o	dumped 5 saded, shot pi	cks of pe at collar of mud, h 20 sacks	feet t	
Checked hole Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement. PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Ceme cement and 7 s (If additiona KNIGHT CASING	sand to 407 ead, had he ulled 103 nting Compa acks of muc	e character of the loade oints o	dumped 5 saded, shot pi	cks of pe at collar of mud, h 20 sacks	feet t	
Checked hole Checked hole Cement. Cut 3277 and it welded on sur 100 sacks of of cement. PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Ceme cement and 7 s LETE. (If additiona KNIGHT CASING CHASE, KANSAS	sand to 407 lead, had he fulled 103 inting Compa acks of muc	e character of the loade oints o	dumped 5 saded, shot ping 5 ½ 16. Had 23 sacks dwell with with the short ping 10 to	cks of pe at collar of mud, h 20 sacks	feet	
Checked hole Checked hole Cement. Cut 3277 and it welded on sur 100 sacks of of cement. PLUGGING COMP TATE OF	to 4160°, ran off poor boy h came loose. P face, Sun Ceme cement and 7 s (If additiona KNIGHT CASING CHASE, KANSAS KANSAS , COU	sand to 407 ead, had ho ulled 103 j nting Compa acks of muc	e character of the character of the loade oints of the loade oints of the character of the loade oints oints of the loade oints of the loade oints oints oints of the loade oints oint	dumped 5 saded, shot pipe 5 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2	cks of pe at collar of mud, h 20 sacks	feet to	
Checked hole Checked hole Cement. Cut 3277' and it welded on sur 100 sacks of of cement. PLUGGING COMP PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Cemer cement and 7 s (If additional KNIGHT CASING CHASE, KANSAS KANSAS	sand to 407 ead, had ho ulled 103 j nting Compa acks of muc	e character of the character of the loade oints of the character of the ch	dumped 5 sade and depth decided, shot ping 5 5 2 16. Had ad 23 sacks decided well with the shoet of this sheet)	cks of pe at collar of mud, h 20 sacks	feet	
Checked hole Checked hole Cement. Cut 3277' and it welded on sur 100 sacks of of cement. PLUGGING COMP PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Cemer cement and 7 s (If additional KNIGHT CASING CHASE, KANSAS KANSAS	sand to 407 ead, had ho ulled 103 j nting Compa acks of muc	e character of the character of the loade oints of the character of the ch	dumped 5 sade and depth decided, shot ping 5 5 2 16. Had ad 23 sacks decided well with the shoet of this sheet)	cks of pe at collar of mud, h 20 sacks	feet to	
Checked hole Checked hole cement. Cut 3277' and it welded on sur 100 sacks of of cement. PLUGGING COMP FATE OF rell, being first duly sworn on oath	to 4160°, ran off poor boy h came loose. P face, Sun Cemer cement and 7 s (If additional KNIGHT CASING CHASE, KANSAS KANSAS	sand to 407 ead, had ho ulled 103 j nting Compa acks of muc	e character of the character of the loade oints of the character of the ch	dumped 5 saded, shot ping 5 5 2 16. Had ad 23 sacks ad well with with the sheet of this sheet.	cks of pe at collar of mud, h 20 sacks	feet	
Checked hole Checked hole Cement. Cut 3277' and it welded on sur 100 sacks of of cement. PLUGGING COMP PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Cemer cement and 7 s (If additional KNIGHT CASING CHASE, KANSAS KANSAS	sand to 407 ead, had ho ulled 103 j nting Compa acks of muc	e character of the character of the loade oints of the character of the ch	dumped 5 saded, shot pipe 5 52 s. Had ad 23 sacks ad well with the shoet of this sheet.	cks of pe at collar of mud, h 20 sacks	feet to	
Checked hole Checked hole Cement. Cut 3277' and it welded on sur 100 sacks of of cement. PLUGGING COMP PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Cemer cement and 7 s (If additional KNIGHT CASING CHASE, KANSAS KANSAS	sand to 407 ead, had ho ulled 103 j nting Compa acks of muc	e character of the character of the loade oints of the character of the ch	dumped 5 sadd, shot ping 5 ½ 15 . Had ad 23 sacks ad well with the sheet of this sheet of the sh	cks of pe at collar of mud, h 20 sacks ss. er or operator) of therein contained WSAS	feet to	
Checked hole General Cut 3277 and it welded on sur 100 sacks of of cement. PLUGGING COMP PLUGGING COMP TATE OF ell, being first duly sworn on oath, bove-described well as filed and the	to 4160°, ran off poor boy h came loose. P face, Sun Ceme cement and 7 s (If additiona KNIGHT CASING CHASE, KANSAS KANSAS , COU NOEL J. KNIGHT , says: That I have kn at the same are true an	sand to 407 lead, had ho lead,	e character of the character of the loade oints of the loade oints of the character of the loade oints o	dumped 5 saded, shot pipe 5 5 2 15 . Had ad 23 sacks ad well with the shoet of this sheet of the shoet of the	cks of pe at collar of mud, h 20 sacks ss. er or operator) of sherein containe WSAS	of the above-describe	
Checked hole Checked hole Cement. Cut 3277' and it welded on sur 100 sacks of of cement. PLUGGING COMP PLUGGING COMP	to 4160°, ran off poor boy h came loose. P face, Sun Ceme cement and 7 s (If additiona KNIGHT CASING CHASE, KANSAS KANSAS , COU NOEL J. KNIGHT , says: That I have kn at the same are true an	sand to 407 lead, had ho ulled 103 j nting Compa acks of much al description is neces PULLING CO UNTY OF T (conowledge of the ind correct. So he (Signature)	e character of the character of the loade oints of the loade oints of the character of the loade oints o	dumped 5 saded, shot pipe 5 5 2 15 . Had ad 23 sacks ad well with the shoet of this sheet of the shoet of the	cks of pe at collar of mud, h 20 sacks ss. er or operator) of sherein containe WSAS	of the above-describe ed and the log of the	
Checked hole cement. Cut 3277 and it welded on sur 100 sacks of of cement. PLUGGING COMP PLUGGING COMP TATE OF rell, being first duly sworn on oath, bove-described well as filed and the	to 4160°, ran off poor boy h came loose. P face, Sun Ceme cement and 7 s (If additiona KNIGHT CASING CHASE, KANSAS KANSAS , COU NOEL J. KNIGHT , says: That I have kn at the same are true an	sand to 407 lead, had ho lead,	e character of the character of the loade oints of the loade oints of the character of the loade oints o	dumped 5 saded, shot pipe 5 52 s. Had 23 sacks and well with the shoet of this sheet) CHASE, KAN (A	cks of pe at collar of mud, h 20 sacks ss. er or operator) of sherein containe WSAS	of the above-describe ed and the log of the	

WELL LOG

Chief Drilling Co.,

Box 797

67530 Great Bend, Kansas

ELMORE "G" #1

NW SW Section 13-175 2 Whom on the section is a county, Kansas

Contractor: Chief Drilling Co., Inc.

Commenced: Completed: 8-31-67.

8-5/8" @ 407' w/225 sacks 60/40 Pozmix Casing Record:

5-1/2" @ 4159' w/10 bbls. salt flush, 150 sacks 60/40

Salt Saturated Pozmix

<u>FORMATION</u>	FROM	<u>T0</u>		VATION 7 Gr.	
Surface Clay	0	60	2169	9 D.F.	
Shale	60	225		2 K.B.	
Shale & Sand Streaks Shale	225 355	355 890	FORMAT	FORMATION TOPS	
Sand Shale, Shells & Red Bed Anhydrite	890 1115 1434	1115 1434 1466			
Shale & Lime Shale & Shells	1466	1635	Anhydrite	1432 (+ 740)	
	1635	1940	Heebner	3573 (-1401)	
Shale & Lime	1940	2426	Toronto	3593 (-1421)	
Lime	2426	2657	Lansing	3612 (-1440)	
Lime & Shale	2657	3326	Base Kansas City	3906 (-1734)	
Lime	3326	3576	Pawnee	3980 (-1808)	
Shale & Lime	3576	3615	Ft. Scott	4054 (-1882)	
Lime Lime & Shale	3615	3905	Cherokee Shale	4063 (-1891)	
	3905	3981	Ist Sand	Not Developed	
Lime	3981	4062	2nd Sand	4080 (-1908)	
Shale & Sand	4062	4126	3rd Sand	4100 (-1928)	
Chert Rotary Total Depth	4126 4160	4160	Conglomerate Mississippi Total Depth	4117 (-1945) 4126 (-1954) 4161 (-1989)	

STATE OF KANSAS, COUNTY OF BARTON) SS

I hereby certify that the above is a true and correct copy of the Driller's Log of the well drilled in the NW SW Section 13-17S-21W, Ness County, Kansas, to the best of my knowledge and belief.

CHIEF DRILLING CO., INC.

Richard Hoover,

drand sworn to before me this/Ist/day of September, 1967.

Carmen R. Cook, Notary Public

December 12, 1970. on expires: