STATE OF KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION 800 BITTING BUILDING WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

lll7 Union Building Lease Owner Solar Oil Company Address Wichita, Kansas
(Applicant) Lease (Farm Name) Herman Behrens Well No. 2
Well Location C N/2 NW NE Sec. 6 Twp. 20 Rge. 15 (K)-(W)
County Barton Field Name (if any)
Total Depth 3755 Oil OilGas Dry Hole
Was well log filed with application? No . If not, explain:
Log will accompany final plugging record
Date and hour plugging is desired to begin May 23, 1956
Plugging of the well will be done in accordance with the Rules and
Regulations of the State Corporation Commission, or with the approval
of the following exceptions: Explain fully any exceptions desired.
(Use an additional sheet if necessary)
Name of the person on the lease in charge of well for owner.
R. B. McFarland Address Box 538 Great Bend, Kansa
Name of Plugging Contractor Ace Pipe Pulling Company
Address 2905 16th, Great Bend, Kansas
Invoice covering assessment for plugging this well should be sent to 1117 Union Building
Solar Oil Company Address Wichita, Kansas
and payment will be guaranteed by applicant. STATE CORPORATION OF MISSION
MAT 2 1955 Jamesh aux to
Applicant or Acting Agent ONSERVATION DIVISION Wichita, Kanses Date May 23, 1956
LINE 4

PLUGGING
FILE SEC 6 1 20 RISW
BOOK PAGE 64 LINE 4

5-23-1956



STATE OF KANSAS

STATE CORPORATION COMMISSION CONSERVATION DIVISION 211 NORTH BROADWAY WICHITA, KANSAS

May 23, 1956

Well No. 2 Lease Echrons Description CN/2 NW NE 6-20-15W County Darton

File No. 61:-h

Solar Oll Company 1117 Union Hational Bank Fldg. Wichita, Kansas

Contlemn:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. M. Frundege, For 283, Hoisington, Kansas.

STATE CORPORATION COMMISSION CONSERVATION DIVISION

S. S. Greider

WELL PLUGGING SUPERVISOR

cc:

District Plugging Supervisor