STATE CORPORATION COMMISSION
CONSERVATION DIVISION - Plugging Section
130 S. Market, Room 2078
Wichita, Kansas 67202

•

3-23

		API NUM	3ER: <u>15-159-2</u>	0,728 · QQ	
		0 E/2 NE	CHAMITON 01	TOUNGUID 2	<u>OS</u> RANGE <u>9₩</u>
		<u>``</u>		_	
OPERATOR	LICENSE # 5893	660	r4620	_ FEET FROM(SECTION LINE
	Pratt Well Service	_			SECTION LINE
NAME &	P O Box 847	<u> </u>		-	ώ
	Pratt, KS 67124	LEASE NA	ME: <u>Dick Twi</u>	n # D1	<u>IE</u>
		CC	UNTY: Rice	9	
		WE	LL TOTAL DEPTH:	3334	108.3,65.92
		P.	IPE: <u>5</u>	1/2" - 3	259
		SU	RFACE CASING: 8	<u> 5/8"-310</u>	
ABANDONI	ED OIL WELL XX GAS WELL	INPUT WEL	.L SWD	D&A	
OTHER WEL	L AS HEREINAFTER INDICATED:				
	CONTRACTOR: Pratt Well Ser				
ADDRESS:	Pratt, KS> 67124		LICENSE: 589	3	_
				4000	
COMPANY T	D PLUG AT: HOUR: 12:00 DA	Y: 23rd MONT	H: March	/EAR: <u>1999</u>	
DILIGOTNA	PROPOSAL SECTION FROM Two	uls Vomal			
	PROPOSAL RECEIVED FROM: Fran		NIE- 216 672	1201	
	AME: Acid Service			7701	
MEKE: _		<u> bottom 3170-5 1250'-35 sacks</u>			APD
		750' - 35 sacks		~~~~ ′∕∕4 / V §	AS COS GELLA
		<u>750 - 55 580</u> 360' - 0			CURPORATION
		<u> </u>			Λ ~
<u> </u>					APR 0 7 1999
				-	- 1999
PLUGGING	PROPOSAL RECEIVED BY:Jac.	k Luthi		C0	NSERVATIO
					NSERVATION DIVISION WICHITA, KS
PLUGGING	OPERATIONS ATTENDED BY AGENT?	ALL (_XX	ART (NONE {	>
					
	. unite 2.20	DAY: 23rd	MONTH: Ma	ırch	YEAR: 1999
COMPLETED	: HOUR: 3:30	DATE GOLG			
			4801		
ACTUAL P	LUGGING REPORT: Sanded	bottom to 3			
ACTUAL P	LUGGING REPORT: Sanded	bottom to 3	ll_of cas	ing Ran	tubing int
ACTUAL P 5 1/2' 1250'.	LUGGING REPORT: <u>Sanded</u> casing off at 131 Pumped 35 sacks. Po	bottom to 3 0'. Pulled a ulled to 750	ll_of cas	ing Ran	tubing int
ACTUAL P 5 1/2' 1250'.	LUGGING REPORT: Sanded	bottom to 3 0'. Pulled a ulled to 750	ll_of cas	ing Ran	tubing int
ACTUAL P 5 1/2' 1250'.	LUGGING REPORT: <u>Sanded</u> casing off at 131 Pumped 35 sacks. Po	bottom to 3 0'. Pulled a ulled to 750	ll_of cas	ing Ran	
ACTUAL P 5 1/2' 1250'.	LUGGING REPORT: <u>Sanded</u> casing off at 131 Pumped 35 sacks. Po	bottom to 3 0'. Pulled a ulled to 750	ll_of cas	ing Ran	tubing int
ACTUAL P 5 1/2' 1250'.	LUGGING REPORT: <u>Sanded</u> casing off at 131 Pumped 35 sacks. Po	bottom to 3 0'. Pulled a ulled to 750	ll_of cas	ing Ran	tubing int
ACTUAL P 5 1/2' 1250'. 360' C	LUGGING REPORT: Sanded casing off at 131 Pumped 35 sacks. Po irculated cement to su	bottom to 3 O'. Pulled a ulled to 750 rface.	ll_of cas	ing Ran	tubing int
ACTUAL P 5 1/2' 1250'. 360' C	LUGGING REPORT: <u>Sanded</u> casing off at 131 Pumped 35 sacks. Po	bottom to 3 O'. Pulled a ulled to 750 rface.	ll_of cas	ing Ran	tubing int
ACTUAL P 5 1/2' 1250'. 360' C: REMARKS:	LUGGING REPORT: Sanded casing off at 131 Pumped 35 sacks. Pr irculated cement to su Acid Service # 0075	bottom to 3 O'. Pulled a ulled to 750 rface.	ll_of cas	ing Ran	tubing int
ACTUAL P 5 1/2' 1250'. 360' C: REMARKS:	LUGGING REPORT: Sanded casing off at 131 Pumped 35 sacks. Pr irculated cement to su Acid Service # 0075	bottom to 3 O'. Pulled a ulled to 750 rface.	ll of cas	ing Ran	tubing int
ACTUAL P 5 1/2' 1250'. 360' c	LUGGING REPORT: Sanded casing off at 131 Pumped 35 sacks. Pr irculated cement to su Acid Service # 0075	bottom to 3 O'. Pulled a ulled to 750 rface.	ll of cas	ing Ran 35 sack	tubing int
ACTUAL P 5 1/2' 1250'. 360' C: REMARKS:	LUGGING REPORT: Sanded casing off at 131 Pumped 35 sacks. Pr irculated cement to su Acid Service # 0075	bottom to 3 O'. Pulled a ulled to 750 rface.	ll of cas	ing Ran 35 sack	tubing int
ACTUAL P 5 1/2' 1250'. 360' C: REMARKS:	LUGGING REPORT: Sanded casing off at 131 Pumped 35 sacks. Pr irculated cement to su Acid Service # 0075	bottom to 3 O'. Pulled a ulled to 750 rface.	ll of cas	ing. Ran 35 sack	tubing int
ACTUAL P 5 1/2' 1250'. 360' C: REMARKS:	LUGGING REPORT: Sanded casing off at 131 Pumped 35 sacks. Pr irculated cement to su Acid Service # 0075	bottom to 3 O'. Pulled a ulled to 750 rface.	Pumped 1 DID OBS	ing. Ran 35 sack	tubing int