

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Alden E. Branine Address 1609 Hillcrest, Newton, Kansas
(Applicant)

Lease (Farm Name) McGreevy Well No. 2

Well Location SW NW SW Sec. 29 Twp. 20 Rge. 13W(E) (W)

County Barton Field Name (if any) Hiss

Total Depth 3546 Oil Gas Dry Hole

Was well log filed with application? Yes If not, explain: _____

Verbal permission to plug 6-13-56

Date and hour plugging is desired to begin 8 AM 6-14-56

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Roy R. Pool Address Lyons, Kansas

Plugging Contractor R & D Casing Pulling Co.

Plugging Contractor's License No. # 236

Address Box 569 Ellinwood, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Alden E. Branine Address Same

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

Alden E. Branine NOV - 3 1956

by James M. Gould CONSERVATION DIVISION
Applicant or Acting Agent

Date November 1, 1956

PLUGGING
FILE SEC. 29 T. 20 R. 13W
BOOK PAGE 72 LINE 25
STATE CORPORATION COMMISSION

DEC 14 1956 12-14-56

CONSERVATION DIVISION
Wichita, Kansas



15.009.15926.0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

June 20, 1956

Well No.	2
Lease	McCreavy
Description	SW NW SW 29-20-13W
County	Barton
File No.	72-35

Alden E. Franine
1609 Hill Crest
Newton, Kansas

Dear Sir:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. N. Brundage, Box 283, Hoisington, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

By S. S. Greider

S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor