

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
Wichita, Kansas 67217

Rev. 3-15-72
FORM CP-1

RECEIVED
STATE CORPORATION COMMISSION
MAR 26 1974
CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner John O Farmer, Inc.

Address Box 352, Russell, Kansas 67665

Lease (Farm Name) Smith Well No. 1

Well Location NE NW Sec. 21 Twp. 20 Rge. 19 (E) (W) X

County Pawnee Total Depth 4286' Field Name

Oil Well X Gas Well Input Well SWD Well Rotary D & A

Well Log filed with application as required Yes

Date and hour plugging is desired to begin April 15, 1974 Approx.

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

Harold A. Carlson Address 632 E. 7th, Russell, Kansas

Plugging Contractor Rockhold Engineering, Inc License No.

Address Box 698, Great Bend, Kansas 67530

Invoice covering assessment for plugging this well should be sent to:

Name John O. Farmer, Inc.

Address Box 352, Russell, Kansas 67530

and payment will be guaranteed by applicant or acting agent.

Signed: Harold A. Carlson
Applicant or Acting Agent
Prod. Supt.

Date: March 25, 1974

State of Kansas



15.145.20224.0000

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

March 26, 1974

WELL PLUGGING AUTHORITY

Well No.	1
Lease	Smith
Description	NE NW Sec. 21-20S-19W
County	Pawnee
Total Depth	4286'
Plugging Contractor	Rockhold Engineering, Inc.


John O. Farmer, Inc.
P. O. Box 352
Russell, Kansas 67665

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. Leo Massey, P. O. Box 582, Hays, Kansas 67601
is hereby assigned to supervise the plugging of the above named well.