

15.009.14589.0001

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
Wichita, Kansas 67217

Rev. 3-15-72
FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

10-22-76

Lease Owner Southern States Oil Company

Address P. O. Box 1365, Great Bend, Kansas 67530

Lease (Farm Name) Clawson Well No. # 4

Well Location S/2 NW/4 Sec. 17 Twp. 20S Rge. ~~XXXX~~ 11 (W)

County Barton Total Depth 3845 Field Name _____

Oil Well _____ Gas Well _____ Input Well _____ SWD Well X Rotary D & A _____

Well Log filed with application as required Yes

Date and hour plugging is desired to begin 8:00 AM October 27, 1976

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

Lee Roy Legleiter Address P.O. Box 1365
Great Bend, Kansas

Plugging Contractor Not known at this time License No. _____

Address _____

Invoice covering assessment for plugging this well should be sent to:

Name Southern States Oil Company

Address P.O. Box 1365, Great Bend, Kansas 67530

and payment will be guaranteed by applicant or acting agent.

Signed: Lee Roy Legleiter
Applicant or Acting Agent

Date: October 21, 1976

State of Kansas



15.009.14589.0001

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)
245 North Water
WICHITA, KANSAS 67202

October 22, 1976

WELL PLUGGING AUTHORITY

Well No.	4
Lease	Clawson
Description	S/2 NW Sec. 17-20-11W
County	Barton
Total Depth	3845
Plugging Contractor	Not known at this time


Southern States Oil Company
P.O. Box 1365
Great Bend, Kansas 67530

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. Duane L. Rankin, P.O. Box 967, Great Bend, Kansas 67530
is hereby assigned to supervise the plugging of the above
named well.