STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

Please mail approval or correspondence to:
Mr. G. A. Reynolds
P. O. Box 7
Ellinwood, Kansas

WELL PLUGGING APPLICATION FORM File One Copy

P. O. Box 1654
Lease Owner Stanoling Oil and Gas Company Address Oklahoma City, Oklahoma (Applicant)
Lease (Farm Name) E. & M. Jutting Well No. 3
Well Location SE NW NE Sec. 15 Twp. 20 Rge. 11 (R)-(W) L
County Barton Field Name (if any) Chase-Silica
Total Depth 3296 Oil X Gas Dry Hole
Was well log filed with application? No . If not, explain:
Will be forwarded with Well Plugging Record
Date and hour plugging is desired to begin 8:00 a.m. October 19, 1953
Plugging of the well will be done in accordance with the Rules and Regulations
of the State Corporation Commission, or with the approval of the following excep
tions: Explain fully any exceptions desired.
(Use an additional sheet if necessary)
Name of the person on the lease in charge of well for owner
J. P. Yowell Address R. R. 1, Ellinwood, Kansas
Name of Plugging Contractor not designated
Address
Invoice covering assessment for plugging this well should be sent to
G. A. Reynolds Address P. O. Box 7, Ellinwood
and payment will be guaranteed by applicant.
Applicant or Acting Agent
COT Applicant or Acting Agent MCL 34 Police TVAL Date October 7, 1953
October 7, 1953 Wichita, Nancus 10-8-53
The state of the s



STATE OF KANSAS

STATE CORPORATION COMMISSION

CONSERVATION DIVISION 800 BITTING BUILDING WICHITA, KANSAS

October 8, 1953

Well No. 3
Lease E. 2 M. Jutting
Description EM NW NE 15-20-11W
County Farton
File No. 134-13

Stanolind Oil & Gas Co. Pox 7 Sllimwood, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. G. D. Steugh, Box 207, Great Lend, Karsas.

STATE CORPORATION COMMISSION CONSERVATION DIVISION

cc: District Plugging Supervisor