

KCC OIL/GAS REGULATORY OFFICES

Inspection Date 03/08/2018 District: 3 Incident Number: 6032

- New Situation Lease Inspection
 Response to Request Complaint
 Follow-up Field Report

Operator License No: 30345 API: Q3 Q2: Q1:
 Operator Name: Piqua Petroleum Inc. SEC 19 TWP 25 RGE 14 RGEDIR E
 Address: 1331 Xylan Road FSL:
 City: Piqua FEL:
 State: KS Zip Code: 66761-1667 Lease: Akins Well No.: 19, 43 & 71
 Phone contact: 620-468-2681 County: WO

Reason for Investigation:

Request from District #3 Supervisor Troy Russell..

Problem:

Piqua Petroleum Inc. #30345 indicated on their well inventory that they could not locate wells #19, #43 and #71 on the Akins lease. KCC Legal Staff, Lauren Wright requested the information and District #3 Supervisor Troy Russell assigned the investigation to me.

Persons contacted:

None

Findings:

I arrived at the lease at about 1:30 pm on Thursday, March 8, 2018. I found a well located near the well #19 location and the well #71 location. I did not locate a well at or near the #43 well location.

Well #19 API#15-207-19228-00-00 is located at 1097' FSL and 348' FEL the Latitude is 37.85391 and the Longitude is -095.90430

Well #43 I DID NOT find a well at this location or in the vicinity of this location..

Well #71 API#15-207-25381-00-00 is located at 819' FSL and 1501' FEL the Latitude is 37.85315 and the Longitude is -095.90830

Actions / Recommendations

Follow-up Required

Deadline Date:

I will forward the information for the well locations to District #3 Supervisor Troy Russell.

Photo's Taken: 2

RBDMS KGS TA DBF Report Prepared By: John Almond District #3
 T1 DBF District Files Courthouse Position: Compliance Officer

KCC OIL/GAS REGULATORY OFFICES

Additional Findings:

Well #19 API#15-207-19228-00-00 is located at 1097' FSL 348' FEL Latitude 37.85391 Longitude - 095.90430

Picture #1 is attached.

Well #43 could not be located at the location or in the vicinity of the location listed in the RBDMS database. I DID NOT find a well at this location.

Well #71 API#15-207-25381-00-00 is located at 819' FSL 1501' FEL Latitude 37.85315 Longitude - 095.90830

Picture #2 is attached.

KCC DISTRICT III OFFICE FIELD REPORT PHOTO ID FORM



Operator:	Piqua Petroleum Inc.
Lease:	Akins
County:	Woodson
Subject:	Well #19
FSL:	1097'
FEL:	348'
API#:	15-207-19228-00-00
Date:	March 8, 2018
Staff:	Almond

KLN:	30345
Legal:	Section 19, Township 25 S, Range 14 E
PIC ID#:	Picture #1
PIC Orientation:	Facing Southwest
Latitude:	37.85391
Longitude:	-095.90430

Time:	2:00 pm
-------	---------

Additional Information:

Picture #1 shows picture of well #19, API#15-207-19228-00-00 located on the Akins lease. The well looks like 4-1/2" casing completed to the surface as an Alternate II completed well, shut in with a cap and valve. The well is located 107' North and 18' West, from the original footages in RBDMS. I conducted a GPS survey on the well and the actual footages are 1097' from the South line of the section and 348' from the East line of the section. There are no other wells in the immediate vicinity of this well.