

KCC OIL/GAS REGULATORY OFFICES

Date: 08/23/18

District: 1

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058

API Well Number: 15-083-21954-00-00

Op Name: American Warrior

Spot: SE SE SW Sec 10 Twp 23 S Rng 23 E / W

Address 1: P O Box 399

455 Feet from N / S Line of Section

Address 2: _____

2195 Feet from E / W Line of Section

City: Garden City

GPS: Lat: _____ Long: _____ Date: _____

State: Kansas Zip Code: 67846 -

Lease Name: Hubin Well #: 2-10B

Operator Phone #: 620 275 2963

County: Hodgeman

Reason for Investigation:

Alt II cementing

Problem:

None

Persons Contacted:

None

Findings:

8 5/8 @ 265' w/ 190 sx, 5 1/2 @ 4650' w/ 175 sx, Port Collar found at 1390', TD-4650'

Swift Svcs pumped 135 sx SMD thru port collar. Circulated 20 sx to the pit.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

Alt II cementing complete

Verification Sources:

Photos Taken: _____

- RBDMS
- T-I Database
- Other: _____
- KGS
- District Files
- TA Program
- Courthouse

By: Ken Jehlik
ECRS

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

RECEIVED

SEP - 4 2018

KCC DODGE CITY

Form: _____