	API Well Number: 15-091-1902	25 - <u>0</u> 0(70		·	
Kansas Corporation Commission	Spot: SWSWSW Sec			12S R	ang <u>22</u>	\square w
	267	-	Feet from N/ S Line of Section			
District Plugging Report	4710			كسنا	E/ W Line of S	Section
		Long: <u>94.9</u>	<u>43900</u>		te: <u>2/16/12</u>	
	Lease Name: Kilmer (Hicks) County: Johnson	· · ·	Well #: KLM 01 Total Vertical Depth: 675 feet			
		6:				
Operator License No: 101 Op Name: State of Kansas	String DRIVE - Drive Pipe	Size	Depth	Pulled 0	Comments EST.	
Address 1: 130 S. MARKET	PROD - Casing	<u>8.000</u> 2.000	<u>20</u> 675	0		
Address 2:		1.000	588	588		
City: WICHITA						
State: KS Zip Code: 67202 -		-	•			
Well Type: RES - Residential Gas Well (605)	IIIC Danton No.) = 4 = #T! =	As Disses ((12/12 /	
	UIC Docket No.:			to Plug: <u>6</u>	0/13/13 ///	
Plug Co License No.: 3097 Proposal Rcvd from: Mike Kepley	Plug Co. Name: <u>K-W OIL</u> Company Name: <u>K-W</u>	. WELL SEP	VICES, II		Phone: <u>(620) 431</u> -	.2285
Fill well with portland cement from					(020/15/	
Plugging		•				;
Plugging						
Report:						
Plugging Proposal Received By: FRANK GUILFOYLE		Witness T	ype: <u>CO</u>	MP - Comp	lete 100%	
Date/Time Plugging Completed: 6/13/13 /	KCC Agent: FRANK GUI	LFOYLE				
Actual Plugging Report:		Perfs:	Тор	Bottom	Thru	
Move equipment to location. Clear location, to	ees and building. Set up rig	and				
work on getting packer loose. Start pulling 1"						
unload. Get loose and pull 588 ft of 1" and par					. <u> </u>	
ft outside 2" and hit hard. Run 1" inside 2" to wash deeper. Pump Portland cement to surface						
out and top ff well. Pump total of 127 sacks of						
	, ,					
	RECEIVED					
	KANSAS CORPORATION COMMISSIO	ON .				
	AUG 0 2 2013					
	CONSERVATION DIVISION	N				
	WICHITA, KS					
Remarks C						
Contract No. 11/82. Cat. III. Control f	No. 20130026-001. GPS by	T.H. Reg	. Sect.			
NAD83 GPS a by TO	ylor Herman		···	· · · · · · · · · · · · · · · · · · ·		
Plugged Thru: TBG - Tubing		Plugg	ged Due to	Complian	ce Issue: Yes	No
	of 1	2 /	7/	1		
District: 03	Frank 2	with	(Technic	ian)		
		Foi	•	t Plugging .	Report	