Form CP-3 Rev. 6-26-62

KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION AGENT'S REPORT

RECEIVED

J. P. Roberts
Assitant Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

FEB 2 1966 Z-Z-66 COMPENSATION DESIGNATION REPORTS R

Operator's	Full Name	Eason Oi	l Company			·	·			· · · · · · · ·	
Complete Ad	dress:	Box 18755,	Oklahoma	City	, Ok	lahor	na				
Lease Name_	De	wall		· · · · · · · · · · · · · · · · · · ·	W	ell No	•		# 1		
Location	SW N	E	·	_Sec	20	Twp	33	Rge _	18	(E)_	(W) <u></u>
County	Comanc	he		T	otal	Depth	1		5350	1	
Abandoned 0	il Well	Gas Well_	Input	Well_		SWD We	11_		& A	<u> </u>	
Other well	as hereafte	r indicated:						·			
Plugging Co	ntractor:_	Gayle E.	Toland &	Compa	nу		· 	· · · · · · · · · · · · · · · · · · ·	<u> </u>		
Address:	Box 9433	6, Oklahom	a City, O	klahor	na	·	Li	.cense	No.	5	39
Operation C	ompleted:	Hourl 2: 30F	M Day 31s	tM	o nt h	Jaı	n.	_Year	1	966	
The Above w	ell was plu	gged as foll	Lows:			•					
269' of	1 <u>3 3/8" s</u>	urface pip	e, cement	circ	ılat	ed. 2	2600	of	8 5	/8"	surface
pipe, cer	mented wi	th 125 sac	ks. 5350'	of 5	<u>l</u> " 1	ong s	stri	ng,	ceme	nted	with
125 sack	s. Top pe	rferation	5249' . 25	sack	s of	cem	ent	was	pump	ed t	o 5000'.
3225' of	5년" long	Box 18755, Oklahoma City, Oklahoma Dewall Box 18755, Oklahoma City, Oklahoma Dewall Well No. # 1 SW NE Sec. 20 Twp. 33 Rge. 18 (E) (W)W Manche Total Depth 5350' L Gas Well Input Well SWD Well D&A X reafter indicated: OCT: Gayle E. Toland & Company 94336, Oklahoma City, Oklahoma License No. 539 ed: Hourl2: 30PM Day 31st Month Jan. Year 1966 Is plugged as follows: 8" surface pipe, cement circulated. 2600' of 8 5/8" surface d with 125 sacks. 5350' of 5½" long string, cemented with perferation 5249'. 25 sacks of cement was pumped to 5000'. long string was recovered from the hole. 2012' of 8 5/8" was recovered from the hole. Fluid in the hole was bailed bridge plug and rock bridge from 240' to 230', and cemented. Hole was filled with mud to 40', bridge plug and rock bridge O', and cemented with 30 sacks to the base of the cellar. that the above well was plugged as herein stated. NO CED Signed: Well Plugging Supervisor Well Plugging Supervisor Well Plugging Supervisor									
surface	pipe was	recovered	from the	hole.	Flu	id i	n th	e ho	le w	as b	ailed
down to	240', bri	dge plug a	nd rock b	ridge	fro	om 240	0' t	0 23	0',	and	cemented
with 50	sacks. Ho	le was fil	led with	mud t	0 40) , b	ride	e pl	ug a	nd r	ock brid
from 40'	to 30',	and cement	ed with 3	O sac	ks t	o the	e ba	se o	f th	e ce	llar.
I hereby ce	DATE	VOIC		ged as			<u> </u>	ul	ging	Supe	rvisor ()