SHEAHAN #1 AFFIDAVIT OF COMPLETION FORM SIDE ONE (REV) ACO-1 This form shall be filed in duplicate with the Kansas Corporation Commission, 200 Colorado Derby Building, Wichita, Kansas 67202, within ten days after the completion of the well, regardless of how the well was completed. Attach separate letter of request if the information is to be held confidential . If confidential, only file one copy. Information on side one will be of public record and side two will then be held confidential.

Circle one: Oil, Gas, Dry SWD, OWWO, Injection. Type and complete ALL sections.

Applications must be filed for dual completion, commingling, SWD and injection, T.A. Attach wireline logs (i.e. electrical log, sonic log, gamma ray neutron log, etc.). KCC # (316) 263-3238. (Rules 82-2-105 & 82-2-125) OPERATOR TXO Production Corp. API NO. 15-095-21,205-000 200 W. Douglas, Suite 300 COUNTY Kingman ADDRESS Wichita, KS 67202 FIELD North Zenda **CONTACT PERSON Harold R. Trapp PROD. FORMATION N/A LEASE Sheahan PHONE 265-9441 PURCHASER_ N/A WELL NO .___ #1 ADDRESS N/A WELL LOCATION 330 Ft. from South Line and DRILLING H-30, Rig #3 2310 Ft. from West CONTRACTOR Line of ADDRESS 251 N. Water the 1 SEC. 29S TWP. 9W RGE. Wichita, KS 67202 WELL PLAT PLUGGING Same KCC _ CONTRACTOR ADDRESS N/A KGS (Office Use) TOTAL DEPTH 2525' PBTD N/A SPUD DATE 12-11-81 DATE COMPLETED 12-15-81 ELEV: GR 1700 N/A KB 1713 DFDRILLED WITH (VANDE) (ROTARY) (ANTA) TOOLS Amount of surface pipe set and cemented N/A . DV Tool Used? N/A AFFIDAVIT STATE OF KANSAS _____, COUNTY OF SEDGWICK _____ss, I, <u>Mr</u>. Harold R. Trapp OF LAWFUL AGE, BEING FIRST DULY SWORN UPON HIS OATH. DEPOSES THAT HE IS <u>District Geologist</u> (FOR)(XXX TXO Production Corp. OPERATOR OF THE Sheahan LEASE, AND IS DULY AUTHORIZED TO MAKE THIS AFFIDAVIT FOR AND ON THE BEHALF OF SAID OPERATOR, THAT WELL NO. #1 __, 19<u>81</u>__, and that SAID LEASE HAS BEEN COMPLETED AS OF THE 15th DAY OF December ALL INFORMATION ENTERED HEREIN WITH RESPECT TO SAID WELL IS TRUE AND CORRECT. PAMELA S. JOLLIFF FURTHER AFFIANT SAITH NOT. STATEWIDE NOTARY PUBLIC Harvey County, Ks. SUBSCRIBED AND SWORN BEFORE ME THIS DAY OF DOCUMENT

tameQa Sas

NOTARY PUBLIC

**The person who can be reached by phone regarding any questions concerning this information. Within 45 days of completion, a witnessed initial test by the Commission required if the well produces more than 25 BOPD or is located in a Basic Order FOGI LANGUE

MY COMMISSION EXPIRES: _Q/14/81

TDE TWO WELL LOG

Show all Important zones of porosity and contents thereof; cored intervals, and all drill-stem tests, including depth interval tasted, cushion used, time tool open, flowing and shut-in pressures, and recoveries.

FORMATIC	N DESCRIPTION, C	ONTENTS, ETC.		тор	воттом		NAME		DEPTI
LOG TOPS Herington Towanda Ft. Riley Florence Cottonwood Foraker Onaga Indian Cave Wabaunsee RTD LTD Ran O.H. Lo DST #1, 242 IFP/30": 1 ISIP/60": FFP/45": 5	gs :0-54' (Ind: :01-495# 824# :05-705#	;		1632 1758 1807 1853 2161 2310 2426 2441 2478 2525 2525	+81 -45 -94 -140 -448 -597 -713 -728 -765		NAME		
FSIP/90": Rec: 1342'	824#								
Nec: 1342	SW			,					
	·					1			
				(
				,		1			
		/			,				
,								ν.	
				ļ			•		
				P					[
			gara wakani wakazio wajazi	,					
Report of all strin							or (UKX		e and nerce
Purpose of string	Sixe hale drilled	Size casing set (in O.D.)		Setting dopth	ECORD (Sacks		oe and parce additives
									oe and parce additives
Purpose of string	Sixe hale drilled	Size casing set (in O.D.)		Setting dopth			Sacks		oe and parce additives
Purpose of string	Sixe hale drilled	Size casing set (in O.D.)		Setting dopth			Sacks		oe and parce additives
Purpose of string	Sixe hale drilled	Size casing set (in O.D.)		Setting dopth			Sacks		e and parce additives
Purpose of string	Sixe hale drilled	Size casing set (in O.D.)	Weight ibs/ft.	Setting depth			Sacks		oe and parce additives
Purpose of string Surface	Sixe hale drilled	Sizo casing set (in O.D.)	Weight ibs/ft.	Setting depth	Typo cemor	P	Sacks	Тус	pe and parce additives
Purpose of string Surface	Sixe hole drilled 1214 LINER RECOR	Sizo casing set (in O.D.) 8-5/8 ^{II} RD Socks ca	Weight ibs/ft.	Setting dopth 261 1	Type cemen	RFORAT	\$acks 240	DRD DO	oe and parce additives
Purpose of string Surface	Sixe hole drilled 1211 LINER RECOR	Sizo cosing set (in O.D.) 8-5/8" RD	Weight ibs/ft.	Setting dopth 261 1	Type cemen	RFORAT	Sacks 240	Typ	
Purpose of string Surface Top, ft. N/A	Sixe hole drilled 12 1/4 LINER RECOR	Sizo casing set (In O.D.) 8-5/8" RD Socks as	Weight ibs/ft.	Setting dopth 261 1	Type cemen	RFORAT	Sacks 240	DRD DO	
Purpose of string Surface op, ft. N/A	Sixe hole drilled 1211 LINER RECOR	Sizo casing set (In O.D.) 8-5/8" RD Socks as N/	Weight ibs/ft.	Setting dopth 261 1	Type cemen	RFORAT	Sacks 240	DRD DO	
Purpose of string Surface op, ft. N/A	Sixe hole drilled 12111 LINER RECOR	Sizo casing set (in O.D.) 8-5/8** RD Socks as N/	Weight ibs/ft.	Setting dopth 261 1	PE	RFORAT	Sacks 240	DRD DO	
Purpose of string Surface Top, ft. N/A	Sixe hole drilled 1211 LINER RECORD Bottom, ft. N/A TUBING RECORD Setting depth N/A	Sizo casing set (in O.D.) 8-5/8** RD Socks as N/	weight ibs/ft.	Setting dopth 261 1 Shots per N/A	PE	RFORAT	Sacks 240 TION RECO	DRD DO	opth interval
Purpose of string Surface op, ft. N/A	Sixe hole drilled 1211 LINER RECORD Bottom, ft. N/A TUBING RECORD Setting depth N/A	Sizo casing set (In O.D.) 8-5/811 RD Socks cs N/ Packer s N/ ACID, FRACTI	weight ibs/ft.	Setting dopth 261¹ Shots per N/A CEMENT SQUE	PE ft.	RFORAT	Sacks 240 TION RECO	DRD N/A	opth interval
Purpose of string Surface op, ft. N/A	Sixe hole drilled 1211 LINER RECORD Bottom, ft. N/A TUBING RECORD Setting depth N/A	Sizo casing set (In O.D.) 8-5/811 RD Socks cs N/ Packer s N/ ACID, FRACTI	weight ibs/ft.	Setting dopth 261¹ Shots per N/A CEMENT SQUE	PE ft.	RFORAT	Sacks 240 TION RECO	DRD N/A	opth interval
Purpose of string Surface op, ft. N/A	Sixe hole drilled 1211 LINER RECORD Bottom, ft. N/A TUBING RECORD Setting depth N/A	Sizo casing set (In O.D.) 8-5/811 RD Socks cs N/ Packer s N/ ACID, FRACTI	weight ibs/ft.	Setting dopth 261¹ Shots per N/A CEMENT SQUE	PE ft.	RFORAT	Sacks 240 TION RECO	DRD N/A	opth interval
Purpose of string Surface op, ft. N/A	Sixe hole drilled 1211 LINER RECORD Bottom, ft. N/A TUBING RECORD Setting depth N/A	Sizo casing set (In O.D.) 8-5/811 RD Socks cs N/ Packer s N/ ACID, FRACTI	weight ibs/ft.	Setting dopth 261¹ Shots per N/A CEMENT SQUE	PE off.	RFORAT	Sacks 240 TION RECO	DRD N/A	opth interval
Purpose of string Surface op, ft. N/A	Sixe hole drilled 1211 LINER RECORD Bottom, ft. N/A TUBING RECORD Setting depth N/A	Sixo casing set (In O.D.) 8-5/8" RD Socks on N/ Packer s N/ ACID, FRACT	weight ibs/ft.	Setting dopth 261¹ Shots po	PE tt.	RFORAT	Sacks 240 TION RECO	DRD N/A	opth interval
Purpose of string Surface op, ft. N/A N/A N/A N/A N/A N/A	Sixe hole drilled 12411 LINER RECORD Bottom, ft. N/A TUBING RECORD Setting depth N/A Amount	Sixo casing set (In O.D.) 8-5/8" RD Socks on N/ Packer s N/ ACID, FRACT	weight ibs/ft.	Setting dopth 261¹ Shots per N/A CEMENT SQUE	PE ft. Sift, atc.)	RFORAT	Sacks 240 TION RECO F type N/A Gravi N/A	DRD N/A	opth interval
Purpose of string Surface op, ft. N/A N/A N/A	Sixe hole drilled 1211 LINER RECORD Bottom, ft. N/A TUBING RECORD Setting depth N/A Amount	Sixo casing set (In O.D.) 8-5/8" RD Socks on N/ ORD Packer : N/ ACID, FRACT	weight ibs/ft.	Setting dopth 261¹ Shots pe N/A CEMENT SQUE	Typo cemon PE ft. Ilft, etc.)	RFORAT Size	Sacks 240 TION RECO F type N/A Gravi N/A	DRD N/A	opth interval