KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form T-1 June 2000 Form must be Typed Form must be Signed All blanks must be Filled

REQUEST FOR CHANGE OF OPERATOR 165 ± 2001 TRANSFER OF INJECTION OR SURFACE POND PERMIT

Check Applicable Boxess	Effective Date of Transfer: 2/1/2001			
Oil Lease: No. of Wells 2 **				
Gas Lease: No. of Wells**	Lease Name: PLATT "A"			
** Side Two Must Be Completed.	Sec. 1 Twp. 35S R. 13 EVW			
Saltwater Disposal Well - Docket No	Legal Description of Lease: LOT 4, S2 NE4 AND SE4 OF			
Spot Location: feet from N / S Line	SEC. 1-T35S-R13W, CONTAINING 280 ACRES,			
feet from E / W Line	MORE OR LESS			
Enhanced Recovery Project Docket No.				
Entire Project: Yes No	County: BARBER			
Number of Injection Wells**	Production Zone(s): MISSISSIPPI			
Field Name: Hardtner	Injection Zone(s):			
Surface Pond Permit #(API # If Drill Pit)	feet from N / S Line of Section			
,	feet from E / W Line of Section			
Identify: Emergency Pit Burn Pit	Storage Pit Drill Pit			
Past Operator's License No. 32429	Contact Person: CM CRAWFORD			
Past Operator's Name & Address: CRAWFORD OIL & GAS, INC.	Phone: 620-582-2612			
PO BOX 51, COLDWATER, KS. 67029	7-01 01			
	WANGE COM			
Title: PRESIDENT	Signature:			
31080	THE HELLMAN			
New Operator's License No. 31980	Contact Person: TIM HELLMAN			
New Operator's Name & Address: LOTUS OPERATING CO.,LLC	Phone: 316-262-1077			
100 S MAIN ST., STE 520	Oil / Gas Purchaser: BARR ENERGY/ONE OK / PLAINS			
WICHITA, KS. 67202	Date: 2-20-2001			
Title: OWNER	Signature:			
Acknowledgment of Transfer: The above request for transfer of injection	authorization, surface pond permit # has been			
·	pration Commission. This acknowledgment of transfer pertains to Kansas			
Corporation Commission records only and does not convey any ownershi				
	, , , , , , , , , , , , , , , , , , , ,			
is acknowleged as the	is acknowleged as the			
new operator and may continue to inject fluids as authorized by	new operator of the above named lease containing the surface pond			
Docket # Recommended action:	permitted by #			
Date:	Date:			
Authorized Signature	Authorized Signature			

Must Be Filed For All Wells

* Lease Name:	PLATT "A"		* Location: SEC. 1-T35S-R13W			
Well No.	AP! No. (YR DRLD/PRE '67)		Footage from Section Line (i.e. FSL = Feet from South Line)		Well Status (PROD/TA'D/Abandoned)	
1 "A"	1956 /5-007-013	/61980 Circle (FS)/FNL	660 Circle	OIL	PROD.	
2 "A"	15-007-20,285	660 (FSI) FNL	660 (FEL)FWL	OIL	PROD.	
		FSL/FNL	FEL/FWL			
		FSL/FNL	FEL/FWL			
		FSL/FNL	FEL/FWL			
			FEL/FWL			
				· .		
		FSL/FNL	FEL/FWL			
		F\$L/FNL	FEL/FWL			
		FSL/FNL	FEL/FWL			
		FSL/FNL	FEL/FWI	-	4-1-24-2	
		F\$L/FNL	FEL/FWI			
		FSL/FNL	FEL/FWI	-		
		FSL/FNL	FEL/FWI			
		FSL/FNL	FEL/FWI	<u> </u>		
		F\$L/FNL	FEL/FWI	<u> </u>		
			FEL/FW			

A separate sheet may be attached if necessary

^{*} When transferring a unit which consists of more than one lease please file a separate side two for each lease. If a lease covers more than one section please indicate which section each well is located.