District

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form T-1 July 2014 Form must be Typed Form must be Signed All blanks must be Filled

REQUEST FOR CHANGE OF OPERATOR TRANSFER OF INJECTION OR SURFACE PIT PERMIT

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form. Check Applicable Boxes: 06/22/16 Oil Lease: No. of Oil Wells _ Effective Date of Transfer: Gas Lease: No. of Gas Wells _ 1 229886 KS Dept of Revenue Lease No.: Gas Gathering System: Lease Name: Hines Farms Saltwater Disposal Well - Permit No.: ... - SW. SE sec. 14 Twp. 28S R. 19E ▼E W _____ feet from N / S Line Legal Description of Lease: SW SE __feet from __ E / __ W Line Entire Project: Yes No Neosho County: Number of Injection Wells __ Production Zone(s): Cherokee Coals CHEROKEE BASIN COAL AREA Injection Zone(s):_ ** Side Two Must Be Completed. Surface Pit Permit No.: ___1513327090 feet from N / S Line of Section (API No. if Drill Pit, WO or Haul) W Line of Section Type of Pit: Emergency Burn Settling Haul-Off Workover Drilling Stephen Moriarty Past Operator's License No. Contact Person: Postrock Midcontinent Production LLC 405-600-7704 Past Operator's Name & Address: 210 Park Ave, Okla. City, OK 73102 Date: Title: Stephen Moriarty, Bankruptcy Trustee for Postrock Midcontinent Prod Signature: Contact Person: Jim Allen New Operator's License No. .. New Operator's Name & Address: River Rock Operating, LLC Phone: 405-606-7481 211 N. Robinson, Suite 200 Oil / Gas Purchaser: BP Energy RECEIVED Oklahoma City, OK 73102 7/19/16 Vice President - Operations Signature: 1513327090 Acknowledgment of Transfer: The above request for transfer of injection authorization, surface pit permit #_ noted, approved and duly recorded in the records of the Kansas Corporation Commission. This acknowledgment of transfer pertains to Kansas Corporation Commission records only and does not convey any ownership interest in the above injection well(s) or pit permit. is acknowledged as is acknowledged as the new operator and may continue to inject fluids as authorized by the new operator of the above named lease containing the surface pit Permit No.: _______ . Recommended action: permitted by No.: _ Date: Authorized Signature Authorized Signature PRODUCTION DISTRICT Mail to: Past Operator **New Operator**

Side Two

Must Be Filed For All Wells

KDOR Lease	No.: 229886				
	77' T		* Location: _S	W SE 14-28S-19E	
Well No.	API No. (YR DRLD/PRE '67)	Footage from Secti (i.e. FSL = Feet from S		Type of Well (Oil/Gas/INJ/WSW)	Well Status (PROD/TA'D/Abandoned)
14-2	1513327090 <i>-00-01</i>	493 FSL 2141 FE	L	Gas	Producing
		FSL/FNL	FEL/FWL		1
<u> </u>		FSL/FNL	FEL/FWL		
		FSL/FNL	FEL/FWL		
		FSL/FNL	FEL/FWL		
		FSL/FNL	FEL/FWL		MARKET STATE OF THE STATE OF TH
		FSL/FNL	FEL/FWL		***************************************
		FSL/FNL	FEL/FWL		
		FSL/FNL	FEL/FWL		
		FSL/FNL	FEL/FWL		
	-	FSL/FNL	FEL/FWL		
		FSL/FNL	FEL/FWL		8
		FSL/FNL	FEL/FWL		
		FSL/FNL	FEL/FWL		
		FSL/FNL	FEL/FWL		KCC WICHITA
		FSL/FNL	FEL/FWL		JUL 27 2016
		FSL/FNL	FEL/FWL		RECEIVED
		FSL/FNL	FEL/FWL _		
		FSL/FNL	FEL/FWL		
		FSL/FNL	FEL/FWL		
***************************************		FSL/FNL	FEL/FWL	200000000000000000000000000000000000000	
		FSL/FNL	FEL/FWL _		
		FSL/FNL	FEL/FWL _		
		FSL/FNL	FEL/FWL _		

A separate sheet may be attached if necessary

^{*} When transferring a unit which consists of more than one lease please file a separate side two for each lease. If a lease covers more than one section please indicate which section each well is located.

Kansas Corporation Commission Oil & Gas Conservation Division

Form KSONA-1 July 2014 Form Must Be Typed Form must be Signed All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

OPERATOR: License # 35341	W. D. C.		
Name: River Rock Operating, LLC	Well Location:		
Address 1: 211 North Robinson			
Address 2: Suite 200	County Neosho		
Address 2: Oklahoma City OK 73102	Lease Name: Hines Farms Well # 14-2		
City: Oklahoma City State: OK Zip: 73102 +	If filing a Form T-1 for multiple wells on a lease, enter the legal description of the lease below:		
Contact Person: 405 606 7483	SW SE		
Phone: (403) 600-7401 Fax: (403) 600-7403	TF.		
Phone: (405) 606-7481	ark.		
Surface Owner Information:	Ton.		
Name: HINES FARMS INC	When filing a Form T-1 involving multiple surface owners, attach an additional		
Address 1:	sheet listing all of the information to the left for each surface owner. Surface		
Address 2: 13350 160TH RD	owner information can be found in the records of the register of deeds for the county, and in the real estate property tax records of the county treasurer.		
City: ERIE State: KS Zip; 66733 +	*		
the KCC with a plat showing the predicted locations of lease roads, tan	odic Protection Borehole Intent), you must supply the surface owners and k batteries, pipelines, and electrical lines. The locations shown on the plat on the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted.		
Select one of the following:			
CP-1 that I am filing in connection with this form; 2) if the form form; and 3) my operator name, address, phone number, fax, a	ocated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form being filed is a Form C-1 or Form CB-1, the plat(s) required by this		
	of the surface owner by filling out the top section of this form and		
If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-	fee with this form. If the fee is not received with this form, the KSONA-1 will be returned.		
hereby certify that the statements made herein are true and correct to	the best of my knowledge and belief.		
7/19/16	Vice President - Operations		