Authorized Signature

Authorized Signature
Form T1 7/94

## MUST BE FILED FOR ALL WELLS

*LEASE NAME	Klingberg OWWO	*LOCATION:	*LOCATION: NE/4 Sec. 34-285-11W	-11W	TYPE OF WELL	WELL STATUS
WELL NO.	(IN DIVID) IND SO				(MSW/UNI	ABANDONED)
	August, 1952	2970	Circle FSL/XXXX 2310	Circle FEL/KWXX	Gas	Producing
			FSL/FNL	FEL/FWL		
\$. s= 1			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		1
			FSL/FNL	FEL/FWL		I
			FSL/FNL	FEL/FWL		Ī
			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		
			FSL/FNL	FEL/FWL		

## A SEPARATE SHEET MAY BE ATTACHED IF NECESSARY