

County: Geary Fraction SW SW SW Sec. 33 T 10 S R 5 (E/W)

CORRECTION(S) TO WATER WELL COMPLETION RECORD (WWC-5)
(to rectify lacking or incorrect information)

Owner: U. S. Army

Location was listed as:

Section-Township-Range: _____

Fraction ($\frac{1}{4}$ $\frac{1}{4}$ $\frac{1}{4}$): _____

Location changed to:

Other changes: Initial statements: Riley County

Changed to: Geary County

Comments: _____

Verification method: Legal description, position on plat map, and mapping tool on KGS website.

Submitted by: _____ initials: DRJ date: 10/3/2012
to: Kansas Geological Survey, Data Resources Library, 1930 Constant Ave., Lawrence, KS 66047-3726
to: Kansas Dept of Health & Environment, Bureau of Water, 1000 SW Jackson, Suite 420, Topeka, KS 66612-1367.

