CORRECTION(S) TO WATER WELL RECORD (WWC-5)

(to rectify lacking or incorrect information)	
---	--

Location listed as:	County: Geary Location changed to:
Section-Township-Range: None Given	29-115-6E
Fraction (1/4 1/4 1/4):	W2 SE NE SW
Other changes: Initial statements: Riley County	
Changed to: Geary County	
Comments: Legal description determination Public Land Survey System of	ed by projecting normal over Fort Riley.
verification method: Latitude and longitude	
1:24,000 topo. map.	initials: 12 date: 5/19/2006

submitted by: Kansas Geological Survey, Data Resources Library, 1930 Constant Ave., Lawrence, KS 66047-3726 to: Kansas Dept of Health & Environment, Bureau of Water, 1000 SW Jackson, Suite 420, Topeka, KS 66612-1367.

LOCATION OF WATER WELL:			KSA 82a-1212 ID I	NODCF 93-16
	Fraction	Section Number	Township Number	Range Number
nty: Riley	1/4 1/4 1/4			E/W
ance and direction rom nearest town or	•			
Trong 39°03'40	0.574"N 96°	47' 26, 346'	' ω	
WATER WELL OWNER: FT KI)	ey Directorate of	F Environment	t & Safety	
WATER WELL OWNER: FT RIN RR #, St. Address, Box #: Bldg 4 City, State, ZIP Code : Ft	NIRY NO	Application Number:	Division of Water Resour	rces
MARK WELL'S LOCATION WITH	4 DEPTH OF WELL	_		
AN "X" IN SECTION BOX:	WELL'S STATIC WATER	RLEVEL 42.7th		
	WELL WAS USED AS:			
NWNE	1 Domestic	5 Public Water Supply	9 Dewate	ring
	2 Irrigation 3 Feedlot	6 Oil Field Water Supply7 Domestic (Lawn & Ga		
E	4 Industrial	8 Air Conditioning	,	
SW SE	Was a chemical / bacteriolog If yes, mo/day/yr sample was			No
	Water Well Disinfected: Yes	s No		
S				
TYPE OF BLANK CASING USED:				
	rought 7 Fiberglas bestos-Cement 8 Concrete	,		
Blank casing diameter	Was casing pulled? urface ir			uch 4. 9
GROUT PLUG MATERIAL: 1 N	leat cement 2 Cement grout	3 Bentonite 4 Ot	ner 5% Bento	nite-Coment 600
G	ft. to ft.,	Fromft. to	ft., From	to ft.
What is the nearest source of possible		44 Final atomics	40.045.55/55	
1 Septic tank2 Sewer lines	6 Seepage pit 7 Pit privy	11 Fuel storage12 Fertilizer storage	16 Other (spe	ecity below)
3 Watertight sewer lines4 Lateral lines	8 Sewage lagoon 9 Feedyard	13 Insecticide storage14 Abandoned water we	all	
5 Cess pool	10 Livestock pens	15 Oil well/Gas well	, "	
Direction from well?	How many f	eet? SOO		
POM TO DI	LUGGING MATERIALS	_		
2 2 2 1 2 1 1				
3,2 3'5% Ben	onito-Cement 60	ont		
3' 0' Top	Soil			
1 1				
				!
				<u> </u>
				:
				!
CONTRACTOR'S OF LANDOWN (mo/day/year)	2	and this record is true	to the best of my knowle	edge and belief. Kansas
(mo/day/year)	2	and this record is true	to the best of my knowle	edge and belief. Kansas
(mo/day/year)	e business name ofU.S.	ACEThis Wate	to the best of my knowler Well Record was com	edge and belief. Kansas pleted on (mo/day/year)
(mo/day/year)	b business name ofU.S. I point pen. Please press firm	A C This Wate	to the best of my knowler Well Record was com	edge and belief. Kansas pleted on (mo/day/year)