

County: Butler Fraction NW SE SE Sec. 4 T 27 S R 4 (E/W)

CORRECTION(S) TO WATER WELL COMPLETION RECORD (WWC-5)
(to rectify lacking or incorrect information)

Owner: Ball Heating

Location was listed as:

Section-Township-Range: 45-4E

Fraction ($\frac{1}{4}$ $\frac{1}{4}$ $\frac{1}{4}$): SE SE NW

Location changed to:

4-27S-4E

NW SE SE

Other changes: Initial statements: _____

Changed to: _____

Comments: _____

Verification method: written description, Butler County online parcel search,
and mapping tool & aerial photos on KGS website.

initials: DRJ date: 12/12/2013

Submitted by: Kansas Geological Survey, Data Resources Library, 1930 Constant Ave., Lawrence, KS 66047-3726
to: Kansas Dept of Health & Environment, Bureau of Water, 1000 SW Jackson, Suite 420, Topeka, KS 66612-1367.

