		<u> </u>		R WELL RECORD	Form WWC-5	KSA 82a-	·-·-	- OPY	Durton File
_		ER WELL:			1	ion Number	Township N		Range Number
County:	SEI	HARVEY	SW 1/4	NW 1/4 ddress of well if loca	SW 1/4	14	T ^ 23	S	R 3 W / Æ/W
				ry, $1\frac{1}{2}$ North		ما			
			WK Farms	y, 12 North	on East Sic				
_	R WELL OW		layton D. K	'aufman			Doord of	A	Division of Water Baseries
-	Address, Box , ZIP Code			ox 90 Ne	wton Kanga	as 6711	1.		Division of Water Resource
City, State	E WELL'S L	CATION WITH	dice I, bo	70 NE	130				
AN "X"	IN SECTION	BOX:	4) DEPTH OF C	OMPLETED WELL.	37	. ft. ELEVAT	TION:		3
- г		<u>'</u>	Depth(s) Ground	water Encountered	37			ft. 3	3
† I	i 1								
i -	NW	NE							ımping gpm
<u> </u>	!	! ! !						•	umping gpm I. to
₹ w }				FO BE USED AS:	5 Public water		8 Air conditioning		
-	y i I	i	1 Domestic						Other (Specify below)
-	1 sw	SE			7 Lawn and o	arden onlv. 1	Observation w	ell	Other (opecity below)
] [-		Was a chemical	bacteriological sampl	e submitted to De	partment? Ye	s No	X If yes	, mo/day/yr sample was sub
ī _			mitted				er Well Disinfecto		
5 TYPE (OF BLANK C	ASING USED:		5 Wrought iron	8 Concre	to tile	CASING IC		dClampedX .
1 St	eel	3 RMP (SI	R)	6 Asbestos-Cemer	nt 9 Other (specify below)		led
2 P\	/C	4 ABS	•	6 Asbestos-Cemer 7 Fiberglass	Transite		, 	Thre	aded
Blank casi	ng diameter	16	.in. to	. 65 . ft., Dia	in. to		ft., Dia		in. to ft.
Casing he	ight above la	nd surface	12	.in., weight	37	1bs./f	t. Wall thickness	or gauge N	_{lo.} 3/4''
		R PERFORATIO			7 PV(10 As	bestos-cem	ent
1 St	1 Steel 3 Stainless steel			5 Fiberglass	5 Fiberglass 8 RMP (S		11 Oti	ner (specify)	====)
2 Br	2 Brass 4 Galvanized steel			6 Concrete tile 9 ABS			12 None used (open hole)		
SCREEN	OR PERFOR	RATION OPENIN	IGS ARE:	5 Ga	uzed wrapped		8 Saw cut		11 None (open hole)
1 Cc	ontinuous slo	t 3 M	lill slot	6 Wi	re wrapped		9 Drilled holes		
2 Lo	uvered shutt	er 4 K	ey punched	7 To	rch cut		10 Other (specif	y)	
SCREEN-	PERFORATE	D INTERVALS:							toft.
			From	ft. to	100	ft., Fron	n	ft. f	toft.
(GRAVEL PA	CK INTERVALS:	From						toft.
-			From	ft. to			n		to ft.
_	T MATERIAL			2 Cement grout					
				ft., From	ft. 1				ft. to
		urce of possible							Abandoned water well
	eptic tank	4 Later		7 Pit privy			storage		
	ewer lines	5 Cess	•	8 Sewage I	•		zer storage	16 C	Other (specify below) Apparent
	•	er lines 6 Seep	page pit	9 Feedyard			ticide storage	· voite	Apparent
FROM	from well?		LITHOLOGIC	LOG	FROM	How mar	ny feet?	LITHOLOG	SIC LOG
0	3	Sandy so		100	THOW	-10		LITHOLOG	aic Log
3	13	Clay							
13	30		Sand & Grav	e1					
30	65	Clay							
65	130		arse Sand &	Gravel					
	1 20								
	-								
	,	***							
				,,					
								11	
7 CONT	RACTOR'S	OR LANDOWNE	R'S CERTIFICAT	ION: This water wel	l was (1) constru	cted. (2) reco	nstructed or (3)	plugged un	der my jurisdiction and wa
completed	on (mo/day	vear) 6	-25-84	TOTAL PRINCIPALICIT WOL	=======	and this reco	rd is true to the b	est of my kr	nowledge and belief. Kansa
	. S. (IIIO/Gay						on (mo/day/yr) .		
Water We	II Contractor	s License No.	430				() () () ()		
Water We	Il Contractor	s License No me of Harp \	230	Service, Inc	•				
under the	business na	me of Harp typewriter or ball	We11& Pump point pen, PLEAS	Service, Inc SE PRESS FIRMLY	and PRINT clear	by (signat	ture) ///// n blanks, underlin	e of circle th	ne correct answers. Send to
under the INSTRUC three copi	business na TIONS: Use es to Kansas	me of Harp typewriter or ball Department of H	We11& Pump point pen, PLEAS ealth and Environ	Service, Inc SE PRESS FIRMLY	and PRINT clear	by (signat y. Please fill in	ture) ///// n blanks, underlin	e of circle th	rnold
under the INSTRUC three copi	business na TIONS: Use es to Kansas	me of Harp typewriter or ball	We11& Pump point pen, PLEAS ealth and Environ	Service, Inc SE PRESS FIRMLY	and PRINT clear	by (signat y. Please fill in	ture) ///// n blanks, underlin	e of circle th	ne correct answers. Send to
under the INSTRUC three copi	business na TIONS: Use es to Kansas	me of Harp typewriter or ball Department of H	We11& Pump point pen, PLEAS ealth and Environ	Service, Inc SE PRESS FIRMLY	and PRINT clear	by (signat y. Please fill in	ture) ///// n blanks, underlin	e of circle th	ne correct answers. Send to