

**CORRECTION(S) TO WATER WELL RECORD (WWC-5)**

(to rectify lacking or incorrect information)

Location listed as:

Section-Township-Range: 22-26S-36W

Fraction (  $\frac{1}{4}$   $\frac{1}{4}$   $\frac{1}{4}$  ): SE NW NE

County: Kearny

Location changed to:

27-24S-36W

NE SE NW NE

Other changes: Initial statements: \_\_\_\_\_

Changed to: \_\_\_\_\_

Comments: \_\_\_\_\_

verification method: Attached site location map, and mapping tool  
on KGS website.

initials: DRL date: 9/18/2007

submitted by: Kansas Geological Survey, Data Resources Library, 1930 Constant Ave., Lawrence, KS 66047-3726  
to: Kansas Dept of Health & Environment, Bureau of Water, 1000 SW Jackson, Suite 420, Topeka, KS 66612-1367.





# GEOCORE INC.

P.O. BOX 386 (785) 828-1616 SALINA, KANSAS

## SITE AREA MAP GEOCORE PROJECT NO. 296

DATE ORIGINATED: 04/04  
SCALE: 1"=100'

SITE: FARMER'S COOP LAKIN  
LOCATION: LAKIN, KANSAS  
SPOT: SEC 27, T24S, R36W

MW, SE, NW, NE  
DRAFTER: RLR

FILE: CLEARMON.dwg

☉ MONITORING WELL  
 ● EXISTING WELL

SCALE: 1" = 100'