

CORRECTION(S) TO WATER WELL RECORD (WWC-5)

(to rectify lacking or incorrect information)

County: Ford

Location listed as:

Section-Township-Range: 35-T27S-R25WFraction ($\frac{1}{4}$ $\frac{1}{4}$ $\frac{1}{4}$): SE NW SE

Location changed to:

35-T26S-R25WSE NW SEOther changes: Initial statements: Several monitoring wells in Dodge City were
mis-located 6 miles SouthChanged to: T26S

Comments: _____

verification method: WWCS database and mapquest websiteinitials: DAH date: June 9, 2005submitted by: Kansas Geological Survey, Data Resources Library, 1930 Constant Ave., Lawrence, KS 66047-3726
to: Kansas Dept of Health & Environment, Bureau of Water, 1000 SW Jackson, Suite 420, Topeka, KS 66612-1367.

KSA 82a-1212

1/4