## WATER WELL RECORD KSA 82a-1201-1215

Kansas Department of Health and Environment-Division of Environment (Water well Contractors) Topeka, Kansas 66620

	County	Fraction		Section number		Township number	Range number	
1. Location of well:	Kearny	NE 1/4 SE 1/4 NI	E 1/4	4		т 26 s	r 36 <b>★</b> /w	
R.R. or Street address of well location if in city:				ner of well: r street: state, zip code:		Joe Baker Lakin, Kansas 67860		
4. Locate with "X" in section below: Sketch map:						6. Bore hole dia 9 <u>778</u> in . Completion date Well depth <u>257</u> ft . <u>7=27=76</u>		
NW NE   X   E						7 Cable tool _X Rotary Driven Dug Hollow rod Jetted Bored Reverse rotary  8. Use: _X Domestic Public supply Industry Irrigation Air conditioning Stock		
SW SE S					Lawn Oil field water Other  9. Casing: Material PL Height: Above or Law Threaded Welded Surface In. RMP PVC Weight lbs./ft. Dia. Sin. to 257 ft. depth Wall Thickness: inches or			
1 Mile → 1  5. Type and color of material					То	Dia in. to 22.2 ft. dept	h gage No	
				<del> </del>		10. Screen: Manufacturer's name		
Fine sand				0	45	Type		
Med. to lar. sand				46	85		ft. and <u>21.7</u> ft.	
Gravel, large				86	170	Gravel pack? <u>yes</u> Size ran		
Sandy clay				171	179	11. Static water level: mo./day/yr.  82 ft. below land surface Date 7/21/76		
Gravel with clay streaks				180	205	12. Pumping level below land surfaces: ft. after hrs. pumping g.p.m.		
Large gravel				206	215	ft. after hrs. pumping g.p.m.  Estimated maximum yield g.p.m.		
Sandy clay				216	225	13. Water sample submitted: mo./day/yr.		
Sandy clay with gravel streaks				226	258	Yes XX No II  14. Well head completion: X Pitless adopter	Inches above grade	
						15. Well grouted? *** Ye With: Neat cement Depth: From ft. to _	Bentonite Concrete	
				-		16. Negrest source of possible contamination:  ft		
					$\vdash$	Well disinfected upon completed 17. Pump:	Not installed	
				-		Model number SD19	Aermotor HP_1½_ Volts 220	
						Length of drop pipe 168	_ ft. capacity <del>20</del> _g.p.m.	
						XX Submersible	Turbine	
(Use a second sheet if needed)						Jet Centrifugal	Reciprocating Other	
18. Elevation: 19. Remarks:  Topography:					20. Water well contractor's control of this well was drilled under my is true to the best of my knowled Friesen Windm	jurisdiction and this report ledge and belief.		
X Hill Slope Upland Valley						Business name	Ansas 67864	